

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 17/08/2020

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : GOO CHUON KWAN

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTPV01011802

Accident Date : 12/08/2020

Vehicle No : SLS-5009-B

Make & Model : MAZDA MAZDA5 WAGON 2.0 AT EU6 1998

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	REAR BUMPER <i>de cm</i> ✓	951.40	✓
1	REAR BUMPER REINFORCEMENT <i>bf</i> ✓	311.50	✓
2	REAR BUMPER RETAINER <i>? xsrc</i>	150.60	X
2	REAR BUMPER BRACKET <i>? cm</i> ✓	116.60	58.30
10	REAR BUMPER CLIPS <i>ree</i> ✓	50.00	✓
2	REAR BUMPER REFLECTOR <i>xsrc</i>	170.80	X
1	END PANEL <i>bf</i> ✓	491.10	✓
1	END PANEL TOP GARNISH <i>de</i> ✓	161.40	✓
1	TAILGATE ASSY <i>bf</i> ✓	1,955.00	✓

Date : 17/08/2020

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : GOO CHUON KWAN

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTPV01011802

Accident Date : 12/08/2020

Vehicle No : SLS-5009-B

Make & Model : MAZDA MAZDA5 WAGON 2.0 AT EU6 1998

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	TAILGATE GARNISH <i>de</i>	659.40	✓
1	TAILGATE TRIMBOARD <i>? for</i>	592.80	X
1	REAR LOGO <i>new</i>	86.10	✓
1	EMBLEM - MAZDA 5 <i>new</i>	121.70	✓
1	EMBLEM - SKYACTIV <i>new</i>	99.80	✓
1	TAILGATE LOCK <i>bt</i>	426.50	✓
1	TAILGATE WEATHERSTRIPE <i>new</i>	396.00	✓
1	REAR WINDSCREEN MOULDING <i>new</i>	87.60	✓
2	TAILGATE LAMP RH/LH <i>LH-? / RH-cm</i>	979.80	489.90 ✓
2	TAILLAMP RH/LH <i>RH-? / LH - old damage X SW</i>	1,346.00	X

Date : 17/08/2020

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : GOO CHUON KWAN

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTPV01011802

Accident Date : 12/08/2020

Vehicle No : SLS-5009-B

Make & Model : MAZDA MAZDA5 WAGON 2.0 AT EU6 1998

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	SPARE TYRE PANEL	RESTORE	X
	Sub Total	9154.10	
	Discount 20% On Parts	(1830.82)	
	<u>Special Nett Item</u>		
1	REAR NUMBER PLATE <i>hi</i>	35.00	<i>✓</i>
1	REVERSE SENSOR <i>? no</i>	220.00	<i>200 ✓</i>
1	WINDSCREEN SEALANT <i>ne</i>	50.00	<i>✓</i>
	Sub Total	305.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	1,400.00	<i>800 ✓</i>

FAX :

Make & Model : MAZDA MAZDA5 WAGON 2.0 AT EU6 1998

Excess : 0.00 Add Excess : 0.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PAGE: 4

Date : 16/09/2020

To : EQ INSURANCE COMPANY LIMITED

Attn : Motor Claim Department

FAX :

Owner : GOO CHUON KWAN

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTPV01011802 Accident Date : 12/08/2020

Vehicle No : SLS-5009-B Make & Model : MAZDA MAZDA5 WAGON 2.0 AT EU6 1998

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
List Item			
6	BUMPER RIVET NAIL NEC / (SUPPL)	50.00	50.00
1	REAR BUMPER	951.40	951.40
1	REAR BUMPER REINFORCEMENT	311.50	311.50
2	REAR BUMPER RETAINER	150.60	0.00
2	REAR BUMPER BRACKET	116.60	58.30
10	REAR BUMPER CLIPS	50.00	50.00
2	REAR BUMPER REFLECTOR	170.80	0.00
1	END PANEL	491.10	491.10
1	END PANEL TOP GARNISH	161.40	161.40
1	TAILGATE ASSY	1955.00	1955.00
1	TAILGATE GARNISH	659.40	659.40
1	TAILGATE TRIMBOARD	592.80	0.00
1	REAR LOGO	86.10	86.10
1	EMBLEM - MAZDA 5	121.70	121.70