

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 17/08/2020
To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : GOO CHUON KWAN
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTPV01011802 Accident Date : 12/08/2020

Vehicle No : SLS-5009-B Make & Model : MAZDA MAZDA5 WAGON 2.0 AT EU6 199

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

List Item

1	REAR BUMPER <i>de cm ✓</i>	951.40
1	REAR BUMPER REINFORCEMENT <i>bt ✓</i>	311.50
2	REAR BUMPER RETAINER ?	150.60
2	REAR BUMPER BRACKET ?	116.60
10	REAR BUMPER CLIPS <i>nee ✓</i>	50.00
2	REAR BUMPER REFLECTOR <i>x</i>	170.80
1	END PANEL <i>bt ✓</i>	491.10
1	END PANEL TOP GARNISH <i>de ✓</i>	161.40
1	TAILGATE ASSY <i>bt ✓</i>	1,955.00

Date : 17/08/2020
 To : EQ INSURANCE COMPANY LIMITED
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : GOO CHUON KWAN
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : D19MTPV01011802 Accident Date : 12/08/2020
 Vehicle No : SLS-5009-B Make & Model : MAZDA MAZDA5 WAGON 2.0 AT EU6 1998

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	TAILGATE GARNISH <i>de ✓</i>	659.40	
1	TAILGATE TRIMBOARD <i>?</i>	592.80	
1	REAR LOGO <i>neu ✓</i>	86.10	
1	EMBLEM - MAZDA 5 <i>neu ✓</i>	121.70	
1	EMBLEM - SKYACTIV <i>neu ✓</i>	99.80	
1	TAILGATE LOCK <i>st ✓</i>	426.50	
1	TAILGATE WEATHERSTRIPE <i>neu ✓</i>	396.00	
1	REAR WINDSCREEN MOULDING <i>neu ✓</i>	87.60	
2	TAILGATE LAMP RH/LH <i>LH-? / RH-cm ✓</i>	979.80	
2	TAILLAMP RH/LH <i>RH-? / LH - old damage X</i>	1,346.00	

Date : 17/08/2020

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : GOO CHUON KWAN

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTPV01011802

Accident Date : 12/08/2020

Vehicle No : SLS-5009-B

Make & Model : MAZDA MAZDA5 WAGON 2.0 AT EU6 1998

ESTIMATED REPAIR COST DETAILS

Excess

: 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	SPARE TYRE PANEL RESTORE		
	Sub Total	9154.10	
	Discount 20% On Parts	(1830.82)	
	<u>Special Nett Item</u>		
1	REAR NUMBER PLATE <i>hi</i>	35.00	
1	REVERSE SENSOR <i>?</i>	220.00	
1	WINDSCREEN SEALANT <i>neu</i>	50.00	
	Sub Total	305.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	1,400.00	<i>800</i>

Date : 17/08/2020

To : EQ INSURANCE COMPANY LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : GOO CHUON KWAN

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTPV01011802 Accident Date : 12/08/2020

Vehicle No : SLS-5009-B Make & Model : MAZDA MAZDA5 WAGON 2.0 AT EU6 1998

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO RESPRAY AFFECTED AREAS	1,400.00	1,400 900
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	120.00	
	TO REMOVE AND TRANSFER TAILGATE COMPONENTS	200.00	80
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	30
	RUST PROOFING	50.00	
	Sub Total	3220.00	
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		10,848.28	
		SUB TOTAL	
		GST 7.0 %	759.38
		TOTAL	11,607.66

Remarks:

7 days - 7/18 Resurvey b4 paint

Surveyor's name: RAUL - 4p 900,10068

Principal's name: GOO CHUON KWAN

Survey Date & Time: 17/08/2020 @ 1620