



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	LCV11416/Mr Tan Eyok Ann
	Reg No/Reg Date	SMQ2302Y*ECB19 / 04/11/2019
	Date In/Mileage	/ 0
	Chassis No	KNAPH81BMK5517259
	Engine No	D4HBJH398417
	Make/Model	KIA/SORENTO 2.2 A SR D EGD
	Colour/Trim	4SS / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	20/08/2020/ 10:46		218 / MarsLer	50867

Description of Goods/Services	Qty	Unit Price	Disc%	Amount
M KS 92403 C5 600 LH INSIDE LAMP ASSY- ADD	1.00	827.00	0.00	827.00
Z NOTES SUPPLEMENTARY ITEM				

Estimate

Confirm & accepted by	Parts	827.00
	Labour	0.00
	Standard Menu	0.00
	Specialist Job	0.00
	Others (Lub, etc)	0.00
	Sundry	0.00
	Total (w/o GST)	827.00

Supplementary
Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.