



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 18/08/	Cust No/Name	/Lau Song Leng (Liu Songlong)
	Reg No/Reg Date	SLZ663H / 23/04/201
	Date In/Mileage	18/08/2020/ 0
	Chassis No	MMBSTA13AJH001940
	Engine No	3A92UGT6174
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	21/08/2020/ 12:40		442 / CocoLu	56153
Description of Goods / Services					Amount
E PNT88000 RENEW FRT BUMPER, FRT FENDER RH & LH, FRT SUPPORT PANEL, BONNET, FRT AIRDAM, REPAIR FRT DOOR RH & LH S SPECIALISTJOB WO: 1239216 ACCIDENT TOWED IN ON DATE 15 AUG @17:58 START & COMPLETED TIME @ 19:45 FROM YISHUN AVE1 TO CNC PG 209 *NORMAL TOWING CHARGE \$50 PLUS ADDITIONAL COST FOR ACCIDENT \$10; TOTAL TOWED IN SVC CHARGE \$60					2025.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT AIRDAM, BONNET, FRT FENDER RH & LH FRT SUPPORT PANEL, FRT DOOR RH & LH					2450.00
E PNT88000 REMOVE & INSTALL FRT AIRDAM					80.00
E PNT88000 REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR					100.00
A 54900099 TOP UP AIRCON GAS					80.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM					30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					120.00
M SUNDRY FRT NUMBER PLATE WITH FRAME					50.00
M SUNDRY APPLY SEALANT FOR ACCIDENT FRT PORTION					40.00
E PNT88000 RENEW REAR AIRDAM, REAR BUMPER, REAR END PANEL, BOOTLID REAR FENDER RH & LH, REAR LAMP HOUSING RH & LH, REAR COMPARTMENT EXTN, QTR PANEL, UPR OTR LH & RH, CHASSIS RH, REPAIR CHASSIS LH					6300.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR					60.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892  18/08/	Cust No/Name	/Lau Song Leng (Liu Songlong)
	Reg No/Reg Date	SLZ663H / 23/04/201
	Date In/Mileage	18/08/2020/ 0
	Chassis No	MMBSTA13AJH001940
	Engine No	3A92UGT6174
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	21/08/2020/ 12:40		442 / CocoLu	56153			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								80.00
REMOVE & INSTALL REAR AIRDAM								120.00
E PNT88000								240.00
REMOVE & INSTALL REAR COMPARTMENT TRIMS								80.00
E PNT88000								120.00
REMOVE & INSTALL REAR WINDSCREEN								1000.00
M SUNDRY								225.00
APPLY SEALANT FOR ACCIDENT PORTION								60.00
E PNT88000								80.00
REMOVE & INSTALL REAR SEATS AND CARPETS								50.00
E PNT88000								20.00
TO STRAIGHTEN FRT & REAR CHASSIS								120.00
A 54900099								
RENEW REAR EXHAUST SYSTEM								
M SUNDRY								
REMOVE & INSTALL REAR BOTH WHEEL TO FACILITATE REPAIR								
M SUNDRY								
APPLY SEALANT FOR ACCIDENT PORTION ON REAR PORTION								
M SUNDRY								
REAR NUMBER PLATE WITH FRAME								
M SUNDRY								
Sundry								
B WHEELALIGNMENT								
To Conduct Computerize Full Wheel Alignment								
S SPECIALISTJOB								
TO SUPPLY FRONT LICENSE PLATE WITH FRAME ( RECTANGULAR & BLACK)								
S SUBADJ								
SUB COST ADJUSTMENT FOR ADJUST ORDER (BOTH FRONT & REAR)								
REFER PO:467295 WIPLINE:123								
S SPECIALISTJOB								
TO SUPPLY BOTH FRONT & REAR LICENSE PLATE WITH FRAME								
( RECTANGULAR & BLACK)								
E PNT98000								3150.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 18/08/	<table> <tr> <td>Cust No/Name</td><td>/Lau Song Leng (Liu Songlong)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLZ663H / 23/04/201</td></tr> <tr> <td>Date In/Mileage</td><td>18/08/2020/ 0</td></tr> <tr> <td>Chassis No</td><td>MMBSTA13AJH001940</td></tr> <tr> <td>Engine No</td><td>3A92UGT6174</td></tr> <tr> <td>Make/Model</td><td>MIT/18MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>A06 COOL SILVER MET/ BK BLACK</td></tr> </table>	Cust No/Name	/Lau Song Leng (Liu Songlong)	Reg No/Reg Date	SLZ663H / 23/04/201	Date In/Mileage	18/08/2020/ 0	Chassis No	MMBSTA13AJH001940	Engine No	3A92UGT6174	Make/Model	MIT/18MY ATTRAGE 1.2 CVT	Colour/Trim	A06 COOL SILVER MET/ BK BLACK
Cust No/Name	/Lau Song Leng (Liu Songlong)														
Reg No/Reg Date	SLZ663H / 23/04/201														
Date In/Mileage	18/08/2020/ 0														
Chassis No	MMBSTA13AJH001940														
Engine No	3A92UGT6174														
Make/Model	MIT/18MY ATTRAGE 1.2 CVT														
Colour/Trim	A06 COOL SILVER MET/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	21/08/2020/ 12:40		442 / CocoLu	56153			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
SPRAY PAINT FOR REAR AIRDAM, REAR BUMPER, REAR END PANEL,BOOTLID, REAR COMPARTMENT, REAR FENDER RH & LH, REAR LAMP HOUSING RH & LH REAR PANEL QUOTER TOP RH & LH								
R	FACE,FR BUMPER				1.00	703.00	23.00	541.31
R	MARK,THREE-DIA				1.00	69.00	23.00	53.13
M	COVER,HEADLAMP SUPT PANEL				1.00	62.00	23.00	47.74
R	BRACKET,FR BUMPER,RH				1.00	13.00	23.00	10.01
R	BRACKET,FR BUMPER,LH				1.00	13.00	23.00	10.01
M	GARNISH,FR BUMPER,LH				1.00	127.00	23.00	97.79
M	GARNISH,FR BUMPER,RH				1.00	127.00	23.00	97.79
M	AIR DAM,SIDE,FR LH				1.00	18.00	23.00	13.86
M	AIR DAM,SIDE,FR RH				1.00	18.00	23.00	13.86
R	GRILLE,FR UNDER				1.00	165.00	23.00	127.05
R	GRILLE,RADIATOR				1.00	554.00	23.00	426.58
R	HOOD				1.00	734.00	23.00	565.18
M	HINGE,HOOD,LH				1.00	56.00	23.00	43.12
M	HINGE,HOOD,RH				1.00	56.00	23.00	43.12
R	LATCH,HOOD				1.00	69.00	23.00	53.13
R	INSULATOR,HOOD				1.00	177.00	23.00	136.29
R	FENDER,FR LH				1.00	497.00	23.00	382.69
R	FENDER,FR RH				1.00	497.00	23.00	382.69
R	SHIELD,FR WHEELHOUSE,LH				1.00	98.00	23.00	75.46
R	SHIELD,FR WHEELHOUSE,RH				1.00	98.00	23.00	75.46
R	PANEL ASSY,FR END				1.00	1055.00	23.00	812.35
M	PANEL,HEADLAMP SUPPORT,UPR				1.00	65.00	23.00	50.05
M	COVER,ENG ROOM UNDER,FR				1.00	99.00	23.00	76.23
M	PANEL,AIR GUIDE,LH				1.00	11.00	23.00	8.47
M	PANEL,AIR GUIDE,RH				1.00	11.00	23.00	8.47
M	GARNISH,FR DECK				1.00	178.00	23.00	137.06
M	GARNISH,FR PILLAR,RH				1.00	30.00	23.00	23.10
M	GARNISH,FR PILLAR,LH				1.00	30.00	23.00	23.10
R	HEADLAMP ASSY,RH				1.00	660.00	23.00	508.20
R	HEADLAMP ASSY,LH				1.00	660.00	23.00	508.20

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 18/08/	<table> <tr> <td>Cust No/Name</td><td>/Lau Song Leng (Liu Songlong)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLZ663H / 23/04/201</td></tr> <tr> <td>Date In/Mileage</td><td>18/08/2020/ 0</td></tr> <tr> <td>Chassis No</td><td>MMBSTA13AJH001940</td></tr> <tr> <td>Engine No</td><td>3A92UGT6174</td></tr> <tr> <td>Make/Model</td><td>MIT/18MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>A06 COOL SILVER MET/ BK BLACK</td></tr> </table>	Cust No/Name	/Lau Song Leng (Liu Songlong)	Reg No/Reg Date	SLZ663H / 23/04/201	Date In/Mileage	18/08/2020/ 0	Chassis No	MMBSTA13AJH001940	Engine No	3A92UGT6174	Make/Model	MIT/18MY ATTRAGE 1.2 CVT	Colour/Trim	A06 COOL SILVER MET/ BK BLACK
Cust No/Name	/Lau Song Leng (Liu Songlong)														
Reg No/Reg Date	SLZ663H / 23/04/201														
Date In/Mileage	18/08/2020/ 0														
Chassis No	MMBSTA13AJH001940														
Engine No	3A92UGT6174														
Make/Model	MIT/18MY ATTRAGE 1.2 CVT														
Colour/Trim	A06 COOL SILVER MET/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	21/08/2020/ 12:40		442 / CocoLu	56153		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	LAMP ASSY,FOG,FR LH			1.00	303.00	23.00	233.31
M	LAMP ASSY,FOG,FR RH			1.00	303.00	23.00	233.31
R	TANK,WINDSHIELD WASHER			1.00	74.00	23.00	56.98
M	MOTOR,WINDSHIELD WASHER			1.00	30.00	23.00	23.10
M	HORN			1.00	79.00	23.00	60.83
R	CONDENSER ASSY,A/C REFRIGE			1.00	758.00	23.00	583.66
M	HOSE,A/C COMPR DISCHARGE			1.00	210.00	23.00	161.70
M	PIPE,A/C CONDENSER OUTLET			1.00	305.00	23.00	234.85
M	HOSE,A/C COMPR SUCTION			1.00	231.00	23.00	177.87
M	PANEL,AIR GUIDE			1.00	112.00	23.00	86.24
R	RADIATOR ASSY			1.00	967.00	23.00	744.59
R	TANK ASSY,RADIATOR COND			1.00	42.00	23.00	32.34
R	FAN,COOLING,LH			1.00	77.00	23.00	59.29
R	SHROUD,COOLING FAN			1.00	130.00	23.00	100.10
M	MOTOR,COOLING FAN			1.00	479.00	23.00	368.83
M	DUCT,A/CLNR INTAKE			1.00	131.00	23.00	100.87
M	DUCT,A/CLNR TO THROT BODY			1.00	103.00	23.00	79.31
M	MANIFOLD,INLET			1.00	562.00	23.00	432.74
R	FACE,RR BUMPER			1.00	748.00	23.00	575.96
R	BRACKET,RR BUMPER,RH			1.00	28.00	23.00	21.56
R	BRACKET,RR BUMPER,LH			1.00	28.00	23.00	21.56
R	PANEL,QTR,OTR RH			1.00	763.00	23.00	587.51
M	PANEL,QTR,OTR LH			1.00	755.00	23.00	581.35
R	PANEL,RR COMB LAMP HSG,RH			1.00	60.00	23.00	46.20
R	PANEL,RR COMB LAMP HSG,LH			1.00	60.00	23.00	46.20
R	EXTN,QTR PANEL,UPR OTR RH			1.00	118.00	23.00	90.86
R	EXTN,QTR PANEL,UPR OTR LH			1.00	118.00	23.00	90.86
R	FLOOR,RR			1.00	956.00	23.00	736.12
M	CROSSMEMBER,RR FLOOR,LWR			1.00	255.00	23.00	196.35
R	PANEL,RR END			1.00	425.00	23.00	327.25
R	STOPPER,WINDSHIELD GLASS			1.00	3.00	23.00	2.31
R	SPACER,RR WINDOW			1.00	9.00	23.00	6.93
M	PANEL,TRUNK LID			1.00	791.00	23.00	609.07

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 18/08/	Cust No/Name /Lau Song Leng (Liu Songlong) Reg No/Reg Date SLZ663H / 23/04/201 Date In/Mileage 18/08/2020/ 0 Chassis No MMBSTA13AJH001940 Engine No 3A92UGT6174 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	21/08/2020/ 12:40		442 / CocoLu	56153		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
R	WEATHERSTRIP,TRUNK LID			1.00	157.00	23.00	120.89
R	LATCH,TRUNK LID			1.00	218.00	23.00	167.86
M	HINGE,TRUNK LID,RH			1.00	203.00	23.00	156.31
M	HINGE,TRUNK LID,LH			1.00	203.00	23.00	156.31
R	GARNISH,RR END PANEL			1.00	336.00	23.00	258.72
R	MARK,ATTRAGE			1.00	21.00	23.00	16.17
R	MARK,THREE-DIA			1.00	69.00	23.00	53.13
M	BOARD,LUGGAGE ROOM PARTN			1.00	172.00	23.00	132.44
R	BOARD,TRUNK ROOM FLOOR			1.00	195.00	23.00	150.15
M	TRIM,RR END			1.00	66.00	23.00	50.82
R	TRIM,TRUNK ROOM SIDE,RH			1.00	160.00	23.00	123.20
R	TRIM,TRUNK ROOM SIDE,LH			1.00	160.00	23.00	123.20
R	GROMMET,RR END TRIM			4.00	3.00	23.00	9.24
R	CLIP,RR END TRIM			6.00	3.00	23.00	13.86
R	GROMMET,RR END TRIM			4.00	3.00	23.00	9.24
R	CLIP,RR END TRIM			4.00	3.00	23.00	9.24
R	CLIP,RR BUMPER			12.00	3.00	23.00	27.72
M	REFLECTOR LH			1.00	23.00	23.00	17.71
M	REFLECTOR RH			1.00	23.00	23.00	17.71
R	LAMP ASSY,COMB,RR RH			1.00	335.00	23.00	257.95
R	LAMP ASSY,COMB,RR LH			1.00	335.00	23.00	257.95
M	LAMP ASSY,LICENSE PLATE			2.00	51.00	23.00	78.54
M	BUZZER,KEYLESS OPERATIO,RR			1.00	91.00	23.00	70.07
M	ANT,KEYLESS OPERATION,RR			1.00	96.00	23.00	73.92
M	DUCT,RR VENTILATOR			1.00	30.00	23.00	23.10
M	COVER,RR VENTILATOR			1.00	40.00	23.00	30.80
M	PIPE,EXHAUST TAIL			1.00	603.00	23.00	464.31
M	MUFFLER,EXHAUST MAIN			1.00	784.00	23.00	603.68
R	CLIP,FR BUMPER			6.00	4.00	23.00	18.48
R	RIVET,FR BUMPER			10.00	5.00	23.00	38.50
R	CAP,TAIL LAMP			2.00	3.00	23.00	4.62
M	GROMMET,TAIL LAMP			2.00	3.00	23.00	4.62
M	UNPAINTED BODYKITS			1.00	1643.00	20.00	1314.40

Confirm &amp; accepted by

Nett 34,596.37  
 7% GST on 34596.37 2421.75  
**Total Payable 37,018.12**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.