



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 18/08/	Cust No/Name /Lau Song Leng (Liu Songlong) Reg No/Reg Date SLZ663H / 23/04/201 Date In/Mileage 18/08/2020/ 0 Chassis No MMBSTA13AJH001940 Engine No 3A92UGT6174 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	25/08/2020/ 16:11		442 / CocoLu	56153

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, FRT FENDER RH & LH, FRT SUPPORT PANEL, BONNET, FRT AIRDAM, REPAIR FRT DOOR RH & LH S SPECIALISTJOB WO: 1239216 ACCIDENT TOWED IN ON DATE 15 AUG @17:58 START & COMPLETED TIME @ 19:45 FROM YISHUN AVE1 TO CNC PG 209 *NORMAL TOWING CHARGE \$50 PLUS ADDITIONAL COST FOR ACCIDENT \$10; TOTAL TOWED IN SVC CHARGE \$60				2250.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT AIRDAM, BONNET, FRT FENDER RH & LH FRT SUPPORT PANEL, FRT DOOR RH & LH				2800.00
E PNT88000 REMOVE & INSTALL FRT AIRDAM				100.00
E PNT88000 REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR				100.00
A 54900099 TOP UP AIRCON GAS				80.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY FRT NUMBER PLATE WITH FRAME				50.00
M SUNDRY APPLY SEALANT FOR ACCIDENT FRT PORTION				40.00
E PNT88000 RENEW REAR AIRDAM, REAR BUMPER, REAR END PANEL, BOOTLID REAR FENDER RH & LH, REAR LAMP HOUSING RH & LH, REAR COMPARTMENT EXTN, QTR PANEL, UPR OTR LH & RH, CHASSIS RH, REPAIR CHASSIS LH				6750.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				60.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 18/08/	Cust No/Name /Lau Song Leng (Liu Songlong) Reg No/Reg Date SLZ663H / 23/04/201 Date In/Mileage 18/08/2020/ 0 Chassis No MMBSTA13AJH001940 Engine No 3A92UGT6174 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	25/08/2020/ 16:11		442 / CocoLu	56153			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								100.00
REMOVE & INSTALL REAR AIRDAM								
E PNT88000								300.00
REMOVE & INSTALL REAR COMPARTMENT TRIMS								
E PNT88000								240.00
REMOVE & INSTALL REAR WINDSCREEN								
M SUNDRY								80.00
APPLY SEALANT FOR ACCIDENT PORTION								
E PNT88000								300.00
REMOVE & INSTALL REAR SEATS AND CARPETS								
E PNT88000								1000.00
TO STRAIGHTEN FRT & REAR CHASSIS								
A 54900099								300.00
RENEW REAR EXHAUST SYSTEM								
M SUNDRY								60.00
REMOVE & INSTALL REAR BOTH WHEEL TO FACILITATE REPAIR								
M SUNDRY								200.00
APPLY SEALANT FOR ACCIDENT PORTION ON REAR PORTION								
M SUNDRY								50.00
REAR NUMBER PLATE WITH FRAME								
M SUNDRY								20.00
Sundry								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
E PNT98000								3150.00
SPRAY PAINT FOR REAR AIRDAM, REAR BUMPER, REAR END PANEL,BOOTLID, REAR COMPARTMENT, REAR FENDER RH & LH, REAR LAMP HOUSING RH & LH REAR PANEL QUOTER TOP RH & LH								
R FACE,FR BUMPER					1.00	703.00	23.00	541.31
R MARK,THREE-DIA					1.00	69.00	23.00	53.13
M COVER,HEADLAMP SUPT PANEL					1.00	62.00	23.00	47.74
R BRACKET,FR BUMPER,RH					1.00	13.00	23.00	10.01
R BRACKET,FR BUMPER,LH					1.00	13.00	23.00	10.01

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 18/08/	Cust No/Name /Lau Song Leng (Liu Songlong) Reg No/Reg Date SLZ663H / 23/04/201 Date In/Mileage 18/08/2020/ 0 Chassis No MMBSTA13AJH001940 Engine No 3A92UGT6174 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
KAX00008	Credit	25/08/2020/ 16:11		442 / CocoLu	56153	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
M	GARNISH,FR BUMPER,LH		1.00	127.00	23.00	97.79
M	GARNISH,FR BUMPER,RH		1.00	127.00	23.00	97.79
M	AIR DAM,SIDE,FR LH		1.00	18.00	23.00	13.86
M	AIR DAM,SIDE,FR RH		1.00	18.00	23.00	13.86
R	GRILLE,FR UNDER		1.00	165.00	23.00	127.05
R	GRILLE,RADIATOR		1.00	554.00	23.00	426.58
R	HOOD		1.00	734.00	23.00	565.18
M	HINGE,HOOD,LH		1.00	56.00	23.00	43.12
M	HINGE,HOOD,RH		1.00	56.00	23.00	43.12
R	LATCH,HOOD		1.00	69.00	23.00	53.13
R	INSULATOR,HOOD		1.00	177.00	23.00	136.29
R	FENDER,FR LH		1.00	497.00	23.00	382.69
R	FENDER,FR RH		1.00	497.00	23.00	382.69
R	SHIELD,FR WHEELHOUSE,LH		1.00	98.00	23.00	75.46
R	SHIELD,FR WHEELHOUSE,RH		1.00	98.00	23.00	75.46
R	PANEL ASSY,FR END		1.00	1055.00	23.00	812.35
M	PANEL,HEADLAMP SUPPORT,UPR		1.00	65.00	23.00	50.05
M	COVER,ENG ROOM UNDER,FR		1.00	99.00	23.00	76.23
M	PANEL,AIR GUIDE,LH		1.00	11.00	23.00	8.47
M	PANEL,AIR GUIDE,RH		1.00	11.00	23.00	8.47
M	GARNISH,FR DECK		1.00	178.00	23.00	137.06
M	GARNISH,FR PILLAR,RH		1.00	30.00	23.00	23.10
M	GARNISH,FR PILLAR,LH		1.00	30.00	23.00	23.10
R	HEADLAMP ASSY,RH		1.00	660.00	23.00	508.20
R	HEADLAMP ASSY,LH		1.00	660.00	23.00	508.20
M	LAMP ASSY,FOG,FR LH		1.00	303.00	23.00	233.31
M	LAMP ASSY,FOG,FR RH		1.00	303.00	23.00	233.31
R	TANK,WINDSHIELD WASHER		1.00	74.00	23.00	56.98
M	MOTOR,WINDSHIELD WASHER		1.00	30.00	23.00	23.10
M	HORN		1.00	79.00	23.00	60.83
R	CONDENSER ASSY,A/C REFRIGE		1.00	758.00	23.00	583.66
M	HOSE,A/C COMPR DISCHARGE		1.00	210.00	23.00	161.70
M	PIPE,A/C CONDENSER OUTLET		1.00	305.00	23.00	234.85

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 18/08/	Cust No/Name /Lau Song Leng (Liu Songlong) Reg No/Reg Date SLZ663H / 23/04/201 Date In/Mileage 18/08/2020/ 0 Chassis No MMBSTA13AJH001940 Engine No 3A92UGT6174 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	25/08/2020/ 16:11		442 / CocoLu	56153
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M HOSE,A/C COMPR SUCTION		1.00	231.00	23.00	177.87
M PANEL,AIR GUIDE		1.00	112.00	23.00	86.24
R RADIATOR ASSY		1.00	967.00	23.00	744.59
R TANK ASSY,RADIATOR COND		1.00	42.00	23.00	32.34
R FAN,COOLING,LH		1.00	77.00	23.00	59.29
R SHROUD,COOLING FAN		1.00	130.00	23.00	100.10
M MOTOR,COOLING FAN		1.00	479.00	23.00	368.83
M DUCT,A/CLNR INTAKE		1.00	131.00	23.00	100.87
M DUCT,A/CLNR TO THROT BODY		1.00	103.00	23.00	79.31
M MANIFOLD,INLET		1.00	562.00	23.00	432.74
R FACE,RR BUMPER		1.00	748.00	23.00	575.96
R BRACKET,RR BUMPER,RH		1.00	28.00	23.00	21.56
R BRACKET,RR BUMPER,LH		1.00	28.00	23.00	21.56
R PANEL,QTR,OTR RH		1.00	763.00	23.00	587.51
M PANEL,QTR,OTR LH		1.00	755.00	23.00	581.35
R PANEL,RR COMB LAMP HSG,RH		1.00	60.00	23.00	46.20
R PANEL,RR COMB LAMP HSG,LH		1.00	60.00	23.00	46.20
R EXTN,QTR PANEL,UPR OTR RH		1.00	118.00	23.00	90.86
R EXTN,QTR PANEL,UPR OTR LH		1.00	118.00	23.00	90.86
R FLOOR,RR		1.00	956.00	23.00	736.12
M CROSSMEMBER,RR FLOOR,LWR		1.00	255.00	23.00	196.35
R PANEL,RR END		1.00	425.00	23.00	327.25
R STOPPER,WINDSHIELD GLASS		1.00	3.00	23.00	2.31
R SPACER,RR WINDOW		1.00	9.00	23.00	6.93
M PANEL,TRUNK LID		1.00	791.00	23.00	609.07
R WEATHERSTRIP,TRUNK LID		1.00	157.00	23.00	120.89
R LATCH,TRUNK LID		1.00	218.00	23.00	167.86
M HINGE,TRUNK LID,RH		1.00	203.00	23.00	156.31
M HINGE,TRUNK LID,LH		1.00	203.00	23.00	156.31
R GARNISH,RR END PANEL		1.00	336.00	23.00	258.72
R MARK,ATTRAGE		1.00	21.00	23.00	16.17
R MARK,THREE-DIA		1.00	69.00	23.00	53.13
M BOARD,LUGGAGE ROOM PARTN		1.00	172.00	23.00	132.44

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 18/08/	Cust No/Name /Lau Song Leng (Liu Songlong) Reg No/Reg Date SLZ663H / 23/04/201 Date In/Mileage 18/08/2020/ 0 Chassis No MMBSTA13AJH001940 Engine No 3A92UGT6174 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	25/08/2020/ 16:11		442 / CocoLu	56153
Description of Goods / Services					
		Qty	Unit Price	Disc%	Amount
R BOARD,TRUNK ROOM FLOOR		1.00	195.00	23.00	150.15
M TRIM,RR END		1.00	66.00	23.00	50.82
R TRIM,TRUNK ROOM SIDE,RH		1.00	160.00	23.00	123.20
R TRIM,TRUNK ROOM SIDE,LH		1.00	160.00	23.00	123.20
R GROMMET,RR END TRIM		4.00	3.00	23.00	9.24
R CLIP,RR END TRIM		6.00	3.00	23.00	13.86
R GROMMET,RR END TRIM		4.00	3.00	23.00	9.24
R CLIP,RR END TRIM		4.00	3.00	23.00	9.24
R CLIP,RR BUMPER		12.00	3.00	23.00	27.72
M REFLECTOR LH		1.00	23.00	23.00	17.71
M REFLECTOR RH		1.00	23.00	23.00	17.71
R LAMP ASSY,COMB,RR RH		1.00	335.00	23.00	257.95
R LAMP ASSY,COMB,RR LH		1.00	335.00	23.00	257.95
M LAMP ASSY,LICENSE PLATE		2.00	51.00	23.00	78.54
M BUZZER,KEYLESS OPERATIO,RR		1.00	91.00	23.00	70.07
M ANT,KEYLESS OPERATION,RR		1.00	96.00	23.00	73.92
M DUCT,RR VENTILATOR		1.00	30.00	23.00	23.10
M COVER,RR VENTILATOR		1.00	40.00	23.00	30.80
M PIPE,EXHAUST TAIL		1.00	603.00	23.00	464.31
M MUFFLER,EXHAUST MAIN		1.00	784.00	23.00	603.68
R CLIP,FR BUMPER		6.00	4.00	23.00	18.48
R RIVET,FR BUMPER		10.00	5.00	23.00	38.50
R CAP,TAIL LAMP		2.00	3.00	23.00	4.62
M GROMMET,TAIL LAMP		2.00	3.00	23.00	4.62
M UNPAINTED BODYKITS		1.00	1643.00	20.00	1314.40

Confirm & accepted by

7% GST on **Nett** 36,216.37
2535.15

Total Payable 38,751.52

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.