

Shirley Hiew (LKK Auto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 20 August 2020 1:12 pm
To: Rasul (LKKAuto); SUR
Subject: RE: SLZ 663H DOA : 15/08/2020

Hi Rasul,

Please see comments from AIG.

Kindly check updates.

Insurer's Mandate Remarks

• **Newer Car Pricing attached don't belong to this model. To obtain Sales Agreement for this model for MV • Prelim Repair Cost and New Car Price not accurate • Repair Cost exceeded Margin Repair Cost TBA • Sundry should not be reflex at Parts column. Parts Discount less 23% not update • Diagnostic Check & Wheel Alignment Report TBC • Parts Damaged TBC: Fan Cooling, LH, Shield,Fr Wheelhousing RH, LH • Labour Renew/ Repair (Rear) \$6,300 how it derive TBC • Labour Spray Painting (Rear) not quoted • Check & Supplementary damaged photos TBC**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)