LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building, 78 Shenton Way

#09-16

Inspection At

Singapore 079120

51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina Date: 25 Aug 2020

Preliminary Advice

Vehicle No : SLZ663H Accident Date : 15/08/2020 Make : MITSUBISHI ATTRAGE Policy No. : 1800042814 **Assignment Date** : 18/08/2020 **Excess** : S\$0.00 : 20 Date of Inspection Est. Duration of Repair : 18/08/2020

: CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (PANDAN GARDENS)

209 PANDAN GARDENS SINGAPORE 609339

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	41,504.00
Revised Amount	:S\$	28,173.24
Check Items (Estimated)	:S\$	6,430.50
Total	:S\$	34,603.74

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	72,999.00
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	32,168.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	40,831.00
Margin for Repair	:S\$	17,832.00

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Margin for Repair is \$17,832.00, Margin for Repair (New for Old Value) is \$40,831.00.