

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 28 Aug 2020

Preliminary Advice

Vehicle No	: SLZ663H	Accident Date	: 15/08/2020
Make	: MITSUBISHI ATTRAGE	Policy No.	: 1800042814
Assignment Date	: 18/08/2020	Excess	: S\$0.00
Date of Inspection	: 18/08/2020	Est. Duration of Repair	: 20
Inspection At	: CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front and rear portio and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,167.08
Revised Amount	:S\$	26,873.95
Check Items (Estimated)	:S\$	6,442.71
Total	:S\$	33,316.66

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	72,999.00
Pre-Accident Value	:S\$	50,000.00
COE / PARF Rebate	:S\$	32,168.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	40,831.00
Margin for Repair (Pre-Accident Value)	:S\$	17,832.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Margin for repair is \$17,832, Margin for Repair (New for Old Value) is \$40,831.00