



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. NA2004324
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSE
SINGAPORE 189556

INV Date 20/08/2020
Reference NS/INC20008591/T1qf3n2
Code INC4



PROFESSIONAL SERVICE FEE

Vehicle No. SHC 1772M
Insured Veh. SMA 6482T
Claim No. MT/1100087-002
Policy No. 5101294558-02
Accident Date 14/08/2020
Inspection Date 14/08/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'National Assessment Centre Services'

National Assessment Centre Services

HYN




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20008591/T1qf3n2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 20-08-2020	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMA 6482T	Veh. Inspected	SHC 1772M	
Policy No.	5101294558-02	Coverage (\$)	0.00	
Claim No.	MT/1100087-002	Excess (\$)	0.00	
Assign From		Assign Date	14/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHLB41UMHU100053	Colour	BLUE	
Odometer	337962	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	14/08/2020	Inspection Date	14/08/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1772M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR LH	TO REPAIR SEE LABOUR	2,201.10	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	2,171.40	-
1	LHS GARNISH	DEFORMED	403.00	403.00
1	FRONT RH WING MIRROR	NOT NECESSARY	670.00	-
1	REAR BUMPER COVER	TO REPAIR SEE LABOUR	1,106.00	-
1	REAR BUMPER BRACKET LH	NOT NECESSARY	35.60	-
1	RH WHEEL HUB COVER	CUT	107.10	107.10
	LESS 20% DISCOUNT		-1,338.84	-102.02
			5,355.36	408.08
	<u>SPECIAL NETT ITEMS</u>			
1	REAR DOOR COMFORT APP STICKER (SN)	NECESSARY	80.00	80.00
1	REAR FENDER ADVERTISEMENT (SN)	NECESSARY	100.00	100.00
1	REAR DOOR ADVERTISEMENT (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER MAT (SN)	NOT NECESSARY	50.00	-
			330.00	280.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR DOOR LH,REAR FENDER LH AND REAR BUMPER COVER.		720.00	560.00
	SPRAY PAINTING CHARGE.		660.00	600.00
	REMOVE & REFIX DOOR PARTS.	NOT NECESSARY	90.00	-
	REMOVE & REFIX UPHOLSTERY FENDER.	NOT NECESSARY	90.00	-
	CHECK LIGHTING.		60.00	30.00
	TUFF KOTE.		60.00	30.00
			1,680.00	1,220.00
	GRAND TOTAL		7,365.36	1,908.08

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,500.00
---	--	--	-----------------

Report Ref No. NS/INC20008591/T1qf3n2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHC 1772M

INSPECTION





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHC 1772M

RE-INSPECTION

