

WILSON TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC8336T DOA: 13.08.2020
 Make : HYUNDAI
 Model : IONIQ

Date: ###
 Insurance: NTUC
 MVA: JUMANI

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY		367.52	\$459.40
1	REAR BUMPER CENTRE MOULDING		361	\$451.25
1	REAR BUMPER TOW COVER			\$82.70
10	REAR BUMPER CLIP		17.60	\$22.00
1	REAR BUMPER RETAINER LH		44.64	\$55.80
1	REAR FOG LAMP ASSY			\$201.50
<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				
			SUB TOTAL	\$1,272.65
			LESS 20%	\$254.53
			DISCOUNTED TOTAL	\$1,018.12
	REAR NUMBER PLATE		10%	\$25.00
			22.50	\$50.00
	Labour Charge			
	PANEL BEATING			\$400.00
	SPRAYPAINT			\$300.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
	Tanph 92495749 paint		550.	
	24/8/2023m			
	2 days			
	P/P Resurvey before paint			
			TOTAL LABOUR	\$780.00
			ESTIMATE TOTAL	\$1,823.12
			1363.26	
			2 days #	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanph e thurston