



MBM WHEELPOWER PTE. LTD.

YOUR REF.: SMM1353C

OUR REF.: SMN3443H

TO: AIG ASIA PACIFIC INSURANCE PTE. LTD.

CC: MOTOR CLAIMS DEPARTMENT

FAX:

DATE: 18/8/2020
 FROM: Lee Shirley
 FAX: 64525333
 CONTACT: 86865188
 MAKE & MODEL: HONDA VEZEL 1.5X CVT
 CHASSIS NO.: RU11319024
 ENGINE NO.: L15B5569063
 YEAR MADE: 2019
 ACCIDENT DATE: 15 August 2020

*Not Authorized
 Resurvey By paint
 2 days*

MATE FOR VEHICLE NO.: SMM1353C

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	BONNET		1	\$ 1,200.00 X
2	BONNET CENTER SEAL		1	\$ 100.00 X
3	FRONT BUMPER		1	\$ 990.00
4	FRONT BUMPER LOWER GRILLE		1	\$ 150.00 X
5	FRONT BUMPER LOWER TRIM		1	\$ 400.00 X
6	FRONT FOG LAMP LH		1	\$ 250.00 X
7	FRONT FOG LAMP RH		1	\$ 250.00 X
8	FRONT BUMPER FOG LIGHT GARNISH RH		1	\$ 105.00
9	FRONT BUMPER FOG LIGHT GARNISH LH		1	\$ 105.00 X
10	FRONT BUMPER TOWING COVER		1	\$ 60.00 X
11	FRONT BUMPER LOWER SPOILER (RUBBER)		1	\$ 90.00 X
12	FRONT BUMPER REINFORCEMENT		1	\$ 600.00
13	FRONT BUMPER RETAINER LH		1	\$ 75.00 X
14	FRONT BUMPER RETAINER RH		1	\$ 75.00
15	FRONT BUMPER CLIP		10	\$ 50.00
16	FRONT GRILLE		1	\$ 500.00 X
17	FRONT GRILLE CHROME MOULDING		1	\$ 400.00 X
18	FRONT GRILLE (H) EMBLEM		1	\$ 50.00 X
19	FRONT GRILLE INNER COVER		1	\$ 60.00 X
20	FRONT GRILLE CLIP		10	\$ 50.00 X
21	FRONT HEADLAMP LH		1	\$ 1,800.00 X
22	FRONT HEADLAMP RH		1	\$ 1,800.00
TOTAL:				\$ 9,160.00
LESS 20%:				\$ (1,832.00)
PARTS TOTAL:				\$ 7,328.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

MBM WHEELPOWER PTE. LTD.
 160 SIN MING DRIVE, #06-02
 SIN MING AUTOCITY
 t 6262 8888 f 6452 5333
 COMPANY REG. NO : 200204110W

SPECIAL NETT

NUMBER PLATE & HOLDER
BODY SEALANT

1	\$	sn	50.00 X
1	\$	nn	50.00 X

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS
TO CHECK & RECONNECT ALL NECESSARY WIRING
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)
TO SPRAY PAINT ON THE AFFECTED AREAS

\$	2201	1,600.00
\$	151	200.00
\$	nn X	250.00
\$	2202	1,000.00

TOTAL: \$ 10,478.00

7% GST: \$ 733.46

GRAND TOTAL: \$ 11,211.46

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
t 6262 8888 f 6452 5333
COMPANY REG. NO.: 200204110W