

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

17/08/2020

TAN CHING GUAN

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 17/08/2020

Estimated repair cost for vehicle no: SFN280M HONDA CIVIC 1.6 VTI CVT 17'

CHASSIS: MRHFC5650HT000354

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Door Distorted.		\$884.90 ✓
2	2	Front R/H Door Hinge New	\$41.20	\$82.40 +
3	2	Front R/H Door Frame Sticker New	\$38.20	\$76.40 ✓
4	1	Front R/H Door Rain Visor New		\$150.00 80(SW) ✓
5	1	Front R/H Door Outer Handle Assy Ct		\$128.60 ✓
6	1	Front R/H Door Outer Moulding Ct		\$45.30 ✓
7	1	Front R/H Door Inner Lock Dmgd.		\$171.30 ✓
8	1	Front R/H Door Inner Rubber Ct		\$96.40 ✓
9	1	Front R/H Door Side Mirror Assy Ct		\$387.00 ✓
10	1	Front R/H Door Window Motor & Regulator Assy Dmgd		\$386.90 ✓
11	1	Front R/H Door Glass Ct		\$349.00 ✓
12	1	Rear R/H Door Distorted		\$747.40 ✓
13	2	Rear R/H Door Hinge New	\$41.20	\$82.40 +
14	2	Rear R/H Door Frame Sticker New	\$38.20	\$76.40 ✓
15	1	Rear R/H Door Rain Visor New		\$150.00 80(SW) ✓
16	1	Rear R/H Door Outer Handle Assy New		\$128.60 +
17	1	Rear R/H Door Outer Moulding Ct		\$45.30 ✓
18	1	Rear R/H Door Inner Lock New		\$171.30 +
19	1	Rear R/H Door Inner Rubber New		\$96.40 +
20	1	Rear R/H Door Window Motor & Regulator Assy New		\$389.90 +
21	1	Rear R/H Door Glass New		\$349.00 +

Subtotal :- \$4,994.90

3384 90

SN 160

2715 92

Labour charges

To remove & refit front R/H door, lock, rubber, glass, window motor trim board & frame sticker

~~\$280.00~~ 80

To remove & refit rear R/H door, lock, rubber, glass, window motor trim board & frame sticker

~~\$280.00~~ 80

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ 40.

Panel beating

1440

~~\$1,200.00~~ 600.

Spray painting

~~\$1,200.00~~ 600

Subtotal :- \$3,210.00

Total:- \$8,204.90

Adrian Lj
L/s 18/08/20

05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4315 92

L/s: 3.4k

3.4k.