



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7259H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	IONIQVC PANEL ASSY-REAR D	TO REPAIR SEE LABOUR	1,789.90	-
1	IONIQVC MOULDING ASSY-SID	TO REPAIR SEE LABOUR	290.00	-
	LESS 20% DISCOUNT		-415.98	-
			1,663.92	-
<u>NETT ITEMS</u>				
1	APP LOGO REAR DOOR L/R CT (N)	NECESSARY	80.00	80.00
1	(I40) FRT DOOR LOGO CTPL (N)	NECESSARY	75.00	75.00
	LESS 10% DISCOUNT		-15.50	-15.50
			139.50	139.50
<u>LABOUR</u>				
	PANEL BEATING (REPAIR FENDER LH). INCLUSIVE OF THE REPAIR OF IONIQVC PANEL ASSY-REAR D AND IONIQVC MOULDING ASSY-SID.		700.00	480.00
	SPRAYPAINT ON AFFECTED AREA.		850.00	600.00
	TUFF COAT ON AFFECTED PARTS.		50.00	30.00
	TRANSFER OF REAR DOOR LH.	NOT NECESSARY	120.00	-
			1,720.00	1,110.00
GRAND TOTAL			3,523.42	1,249.50

RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,249.50
--	--	--	-----------------

Report Ref No. NS/INC20008600/T1vf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.