

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008601/KDS3Q2

Date: 03/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100491630

Claimant
Vehicle No : SML7610B **Insured Vehicle No :** SGN7317J

Date of Loss: 13/08/2020 Nature of Claim: TP Claim No: 9870759657SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML7610B**

Make & Model: OPEL INSIGNIA GRANDSPORT B16DTH, 1.6 Turbo (A) Engine No: A2183328JSUX0398

Reg. Date: 03/06/2019 (Man. Year: 2019) Chassis No: W0VZM6EF2K1034651

Colour: White Odometer: 93502 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55Z R17 Rear Tyre Size: 225/55Z R17

Front Left Side: Kumho 9 mm Rear Left Side: Kumho 9 mm

Front Right Side: Kumho 9 mm Rear Right Side: Kumho 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repaire's	Adjuster's	Difference	Diff %
Parts	10,400.54	7,612.96	2,787.58	26.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	2,110.00	1,490.00	41.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,000.54	9,722.96	4,277.58	30.55
Approved Total (Overridden) (S\$)		7,750.00		
(S\$)	14,000.54	7,750.00	6,250.54	44.64
+ GST 7.00/7.00% (S\$)	980.04	542.50	437.54	44.65
Nett Amount (S\$)	14,980.58	8,292.50	6,688.08	44.65
+ Loss of Use (8.0 x S\$80.00/day) (S\$)		640.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,934.50		

INSPECTION

Date of Assignment: 18/08/2020

Date Inspected: 18/08/2020 Inspected At:

Munich Autocare Pte Ltd (HQ)
60 Jalan Lam Huat, #02-02/03 Carros
Centre
Singapore 737869

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,150.24 FL	*1,150.24 FL
2	1		*REAR BUMPER REFLECTOR LH	Serviceable	24.96 FL	*- FL
3	1		*REAR BUMPER EXTENSION	Bent	268.32 FL	*268.32 FL
4	1		*BOOT LID	Bent	1,734.72 FL	*1,734.72 FL
5	1		*REAR END PANEL	Bent	434.72 FL	*434.72 FL
6	1		*REAR PANEL LOWER	Repair	427.44 FL	*- FL
7	1		*CHROME REAR LAMP INNER LH	Serviceable	26.00 FL	*- FL
8	6		*REAR BUMPER CLIPS	Necessary	46.20 FS	*46.20 FS
9	6		*FRONT BUMPER CLIPS	Necessary	46.20 FS	*46.20 FS
10	1		*FRONT NUMBER PLATE	Cracked	25.00 FS	*25.00 FS
11	1		*REAR NUMBER PLATE WITH HOLDER	Cracked	50.00 FS	*45.00 FS
12	1		*FRONT BUMPER	Buckled / Dented	1,350.96 FL	*1,350.96 FL
13	1		*FRONT BUMPER IMPACT ABSORBER	Serviceable	477.36 FL	*- FL
14	1		*BUMPER REINFORCEMENT LOWER	Dented	111.28 FL	*111.28 FL
15	1		*ENERGY ABSORBER LH	Serviceable	15.60 FL	*- FL
16	1		*ENERGY ABSORBER RH	Serviceable	15.60 FL	*- FL
17	1		*FRONT BUMPER PANEL SUPPORT	Serviceable	176.80 FL	*- FL
18	1		*RADIATOR GRILLE	Cracked	310.96 FL	*310.96 FL
19	1		*BEZEL CHROME MOULDING	Distorted	284.96 FL	*284.96 FL
20	1		*SUPPORT CENTRE	Serviceable	158.08 FL	*- FL
21	1		*EMBLEM OPEL BLITZ	Necessary	78.00 FL	*78.00 FL
22	1		*BONNET HINGE RH	Repair	138.32 FL	*- FL
23	1		*BONNET HINGE LH	Repair	138.32 FL	*- FL
24	2		*BONNET HINGE ACTUATOR	Activated	1,027.52 FL	*1,027.52 FL
25	1		*BONNET LATCH ASSY	Repair	44.72 FL	*- FL
26	1		*BRACKET BONNET LATCH	Repair	12.48 FL	*- FL
27	1		*BONNET SEAL	Buckled	1,526.72 FL	*1,526.72 FL
28	1		*INSERT CHROME RH	Serviceable	470.08 FL	*- FL
29	1		*INSERT CHROME LH	Serviceable	470.08 FL	*- FL
30	1		*BRACKET RH	Repair	48.80 FL	*- FL
31	1		*BRACKET LH	Repair	48.80 FL	*- FL
32	1		*BUCKLE ASSY SEAT BELT LOWER	Serviceable	398.32 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,537.56	8,440.80
- List Item Discount on L Items 10.00/10.00% (S\$)	1,137.02	827.84
Total Parts (S\$)	10,400.54	7,612.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PUTTY & SPRAY PAINT ALL AFFECTED AREAS	New	1,600.00	1,100.00
2	LABOUR FOR PANEL BEATING ALL AFFECTED AREAS	New	1,400.00	900.00
3	TO APPLY ANTI-RUST	New	150.00	90.00
4	TO CHECK ALL WIRING FOR PROPER FUNCTION	New	200.00	20.00
5	LABOUR FOR REMOVE & REPLACE FRONT DRIVER SAFETY BELT & RESETTNG SYSTEM	New	250.00	0.00
Gross Labour Cost (S\$)			3,600.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >