

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869

Tel: +65 6255 2288 | Fax: +65 6265 5388

Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

ESTIMATION REPORT

Vehicle No : SML7610B
Make & Model : OPEL , INSIGNIA GRANDSPORT
B16DTH,W0VZM6EF2K1034651
Year of Manufacture : 2019

Estimation No. : E20080011
Date : 17/08/2020

*Not Not hoink
Running B& paint*

No.	Description	Qty	U/P	Amt
<u>Section: Remark</u>				
1	AIG ASIA PACIFIC INSURANCE PTE LTD DOA: 13.08.2020	1.00	0.00	0.00
				Amt S\$ 0.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00

<u>Section: Parts</u>				
2	39159652 FRONT BUMPER	1.00	1,350.96	1,350.96 ✓
3	39117745 FRONT BUMPER IMPACT ABSORBER	1.00	477.36	477.36 ?
4	39107472 BUMPER REINFORCEMENT LOWER	1.00	111.28	111.28 ✓
5	39112563 ENERGY ABSORBER LH	1.00	15.60	15.60 ?
6	39108756 ENERGY ABSORBER RH	1.00	15.60	15.60 ?
7	39077621 FRONT BUMPER PANEL SUPPORT	1.00	176.80	176.80 X
8	39107929 RADIATOR GRILLE	1.00	310.96	310.96 ✓
9	13491196 BEZEL CHROME MOULDING	1.00	284.96	284.96 ✓
10	39136418 SUPPORT CENTRE	1.00	158.08	158.08 ?
11	13491204 EMBLEM OPEL BLITZ	1.00	78.00	78.00 ✓
12	39126609 BONNET HINGE RH	1.00	138.32	138.32 X
13	39126608 BONNET HINGE LH	1.00	138.32	138.32 X
14	39169701 BONNET HINGE ACTUATOR	2.00	513.76	1,027.52 ?
15	39118540 BONNET LATCH ASSY	1.00	44.72	44.72 X
16	39107388 BRACKET BONNET LATCH	1.00	12.48	12.48 X
17	39214206 BONNET PANEL	1.00	1,526.72	1,526.72 ✓
18	13491272 INSERT CHROME RH	1.00	470.08	470.08 X
19	13491269 INSERT CHROME LH	1.00	470.08	470.08 X
20	13491383 BRACKET RH	1.00	48.80	48.80 ?
21	13491831 BRACKET LH	1.00	48.80	48.80 ?
22	39141088 BUCKLE ASSY SEAT BELT DRIVER	1.00	398.32	398.32 ?

Continue on next page...

Munich Autocare Pte Ltd

60 Jalan Lam Huat #02-02/03 Carros Centre Singapore 737869
Tel: +65 6255 2288 | Fax: +65 6265 5388
Company Reg. No.: 201832250M | GST Reg. No.: 201832250M

ESTIMATION REPORT

Estimation No. : E20080011
Date : 17/08/2020

Vehicle No : SML7610B
Make & Model : OPEL , INSIGNIA GRANDSPORT
B16DTH,W0VZM6EF2K1034651
Year of Manufacture : 2019

No.	Description	Qty	U/P	Amt	
23	39211015 REAR BUMPER	1.00	1,150.24	1,150.24	✓
24	13460219 REAR BUMPER REFLECTOR LH	1.00	24.96	24.96	?
25	39144798 REAR BUMPER EXTENSION	1.00	268.32	268.32	✓
26	39112803 BOOT LID	1.00	1,734.72	1,734.72	✓
27	39143308 REAR END PANEL	1.00	434.72	434.72	✓
28	39069396 REAR PANEL LOWER	1.00	427.44	427.44	?
29	39080282 CHROME REAR LAMP INNER LH	1.00	26.00	26.00	X
				Amt	S\$
					11,370.16
				Discount (10.00%)	S\$ 999.99
				Subtotal	S\$ 10,233.14
Section: Special nett LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
30	REAR BUMPER CLIPS	6.00	7.70	46.20	✓
31	FRONT BUMPER CLIPS	6.00	7.70	46.20	✓
32	FRONT NUMBER PLATE	1.00	25.00	25.00	✓
33	REAR NUMBER PLATE WITH HOLDER	1.00	50.00	50.00	FSM
34	REVERSE CAMERA	1.00	426.40	426.40	?
				Amt	S\$ 593.80
				Discount (0.00%)	S\$ 0.00
				Subtotal	S\$ 593.80
Section: Labour					
35	LABOUR FOR PUTTY & SPRAY PAINT ALL AFFECTED AREAS	1.00	1,600.00	1,600.00	1100
36	LABOUR FOR PANEL BEATING ALL AFFECTED AREAS	1.00	1,400.00	1,400.00	900
37	TO APPLY ANTI-RUST	1.00	150.00	150.00	900
38	TO CHECK ALL WIRING FOR PROPER FUNCTION	1.00	200.00	200.00	?
39	LABOUR FOR REMOVE & REPLACE FRONT DRIVER SAFETY BELT & RESETTNG SYSTEM	1.00	250.00	250.00	?

Continue on next page...