

Our Job Ref No 305416874
Date : 25.08.20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax :
Attn : Mr TAUFIKH
Vehicle Reg No. SHC2645R CTPL 14.08.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SKR3592M
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges _____
 - Total for Part-By-Part Repair Cost** _____
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,250.00
Final Lumpsum Repair cost \$1,250.00
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature : taufikh
Name : Taufikh
Date : 28/8/20

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305416874
 REGN NO : SHC2645R
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 25.01.2017
 DATE/TIME IN : 15.08.2020 09:55
 ACCIDENT DATE : 14.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1 L	1,106.00	20.00	884.80	de ✓	
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	nu ✓	
0003 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1 L	228.00	20.00	182.40	Rp	1,128 -20%
0004 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	135.70	10.00	122.13	nu	902.40 +172.13 Net
0005 04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	50.00	50.00	nu	1,074.53
						SUB-TOTAL :	1,256.93

JOB NATURE

000 L	PANEL BEATING	350.00	280			510 1,584.53 -20%
0001 23-502	SPRAYPAINT ON AFFECTED AREA	250.00	200			1,267.62
0002 20-22	REMOVE/REFIX REVERSE SENSOR	80.00	30			
						SUB-TOTAL : 680.00

Tanfah 97445749
 WP

12/8/2020 3pm

2 days Lumpsum \$1,250/-

Ready after repair

Tanfah Mahanbun