

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20008607/T1VF3E2

Date: 28/08/2020

REFERENCE

| | | |
|--------------------------------------------------------|----------------------|-----------------------|
| Handling Insurer: Tokio Marine Insurance Singapore Ltd | Policy No: | MR002945 |
| Claimant Vehicle No : SHA7577G | Insured Vehicle No : | SDS3833X |
| Date of Loss: 14/08/2020 | Nature of Claim: | TP Claim No: M2004010 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---------------------------------------|--------------------|-----------------------------------|
| Reg No: | SHA7577G | Engine No: | G4LEKU400500 |
| Make & Model: | HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) | Chassis No: | KMHC851CVLU187486 |
| Reg. Date: | 30/10/2019 (Man. Year: 2019) | Odometer: | 53667 km |
| Colour: | Blue | Engine Capacity: | 1580 cc |
| Market Value/New Car Price: | N/A | Sum Insured (S\$): | Market Value/New Car Price |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|------|-------------------------|-----|--------------------------|------|
| General Condition: | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | Good |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 195/65 R15 | Rear Tyre Size: | 195/65 R15 |
| Front Left Side: | Michelin 6 mm | Rear Left Side: | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts | 1,527.20 | 413.84 | 1,113.36 | 72.90 |
| Miscellaneous Items | 11.00 | 11.00 | 0.00 | 0.00 |
| Labour | 840.00 | 650.00 | 190.00 | 22.62 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 2,378.20 | 1,074.84 | 1,303.36 | 54.80 |
| + GST 7.00/7.00% (S\$) | 166.47 | 75.24 | 91.23 | 54.80 |
| Nett Amount (S\$) | 2,544.67 | 1,150.08 | 1,394.59 | 54.80 |

INSPECTION

| | | |
|-----------------------------|------------------------------|--------------------------------------------------------------------------------------|
| Date of Assignment: | 18/08/2020 Present Location: | ComfortDelGro Engineering Pte Ltd (Loyang) |
| Date Inspected: | 18/08/2020 Inspected At: | ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969 |
| Estimated Period of Repair: | 2.0 days | |

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|-----------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 28 Aug 2020) |
| Parts: 192 | HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SHA7577G) |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Reference | Amount |
|-----|-----|----------|-----------------------|-----------|-----------------------------------------------------------|-----------------|---------------|
| 1 | 1 | | *FRT FENDER RH | Bent | 490.70 FL | - | *490.70 FL |
| 2 | 1 | | *FRT FENDER HYBRID RH | Necessary | 26.60 FL | - | *26.60 FL |
| 3 | 1 | | *WING MIRROR RH | Repair | 1,391.70 FL | - | *- FL |
| | | | | | Sub Total (S\$) | 1,909.00 | 517.30 |
| | | | | | - List Item Discount on L Items 20.00/20.00% (S\$) | 381.80 | 103.46 |
| | | | | | Total Parts (S\$) | 1,527.20 | 413.84 |

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No | Qty | Particulars | Repairer's | Amount |
|----------------------------|-----|----------------------|--------------|--------------|
| Miscellaneous Items | | | | |
| 1 | 1 | OD/TP Case (Insurer) | 11.00 | 11.00 |
| Sub Total (\$) | | | 11.00 | 11.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------------|----------------|----------|---------------|---------------|
| Labour Items | | | | |
| 1 | PANEL BEATING | New | 400.00 | 320.00 |
| 2 | SPRAY PAINTING | New | 400.00 | 300.00 |
| 3 | TUFF KOTE | New | 40.00 | 30.00 |
| Gross Labour Cost (\$) | | | 840.00 | 650.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >