



Vix Auto Pte Ltd
24 Chia Ping Road
Singapore 619977
Email: contact@vixauto.com.sg
Tel: 64552797 Fax: 68628667
UEN / GST REG No.: 201839761R

ESTIMATE

DATE : 21/2/2020
ACC DATE : 20/2/2020
POLICY NO : DMCG19001458

Attention: Motor Claim Department

SHEET NO. 1 OF 2 SHEET

RE: VEHICLE NO: XE4589Y MITSUBISHI FUSO/ CHENG HENG LEE PTE LTD

S/NO	QTY	DESCRIPTION	UNIT PRICE \$	AMOUNT \$
1	✓	FRONT CABIN HEAD - damaged / broken		85,000.00
2	✓	FRONT BUMPER		2,987.70
3	✓	FRONT SIDE CORNER COVER RHS - missing		240.00
4	✓	FRONT BUMPER STEP GARNISH - snapped		289.70
5	✓	FRONT BUMPER CENTER COVER RHS - snapped		76.50
6	✓	FRONT HEADLAMP RHS - missing		1,674.00
7	✓	FOG LAMP RHS - missing		396.70
8	✓	FRONT BUMPER SIDE INNER GARNISH torn		137.00
9	X	FRONT BUMPER REINFORCEMENT		1,200.00
10	✓	FRONT HEADLAMP RHS BRACKET INNER - snapped		397.00
11	✓	FRONT HEADLAMP RHS BRACKET BOTTOM - snapped		217.00
12	✓	FRONT HEADLAMP RHS BRACKET TOP - snapped		195.00
13	✓	FOG LAMP BOTTOM BRACKET - snapped		35.00
14	✓	FRONT SIDE UPPER GARNISH RHS torn		112.00
15	✓	FRONT FENDER SIDE BOTTOM GARNISH RHS torn		672.50
16	✓	STEP BOARD UPPER RHS - damaged SNAPPED		576.80
17	✓	STEP BOARD LOWER RHS - damaged SNAPPED		587.20
18	✓	STEP BOARD BRACKET RHS - snapped		865.00
19	✓	STEP ALUMINIUM PLATE - snapped	270.00	810.00
20	✓	FRONT MUGUARD RHS - damaged		557.00
21	✓	FRONT FENDER INNER SHIELD torn		162.00
22	✓	AIR INTAKE TOP - damaged		1,789.00
23	X	AIR INTAKE CENTER		652.00
24	X	AIR INTAKE LOWER		869.00
25	X	AIR DRYER RHS		1,246.00
26	X	STEERING BOX		3,200.00
27	✓	STEERING COUPLING - jammed		423.00
28	X	HORN		120.00
29	X	FRONT CABIN HEAD ROLLER BAR		1,317.00
30	X	FRONT ROLLER BAR BRACKET	672.00	1,344.00
31	X	FRONT CABIN HEAD ABSORBER	368.00	736.00
32	X	FRONT CABIN HEAD AIR BALLON	289.00	578.00
33	✓	ENGINE WIRE HARNESS - snapped / burst		12,675.00
34	✓	GEARBOX WIRE HARNESS - snapped / burst		12,134.00
35	X	WIRE HARNESS MAIN FUSE BOX	78.00	156.00
36	X	BRAKE AIR HOSE - burst	450.00	1,800.00
37	X	HANDBRAKE AIR HOSE	372.00	744.00
38	✓	MAIN AIR HOSE - burst		462.00
39	X	RADIATOR		5,678.00
40	X	RADIATOR FAN BLADE		423.00
41	X	RADIATOR FAN CLUTCH		2,684.00
42	X	RADIATOR FAN COWLING		789.00
43	X	TURBO INTERCOOLER		8,962.00
44	X	INTERCOOLER HOSE	448.00	896.00
45	X	REAR CABIN HEAD ROLLER BAR		1,841.00
46	X	REAR ROLLER BAR BRACKET		3,789.00
47	X	REAR CABIN HEAD ABSORBER		327.00
48	X	REAR CABIN HEAD AIR BALLON		284.00
49	✓	FRONT DRIVER SEAT - damaged / shredded - 900.00 - (local repair)	25%	6,897.00
				\$ 159,943.10
				\$ 127,457.33

S/NO	QTY	DESCRIPTION	UNIT PRICE	AMOUNT \$
1	X	SPECIAL NET		\$ 25.00
2	X	BRAKE OIL		\$ 30.00
3	X	AUTO OIL		\$ 30.00
4	X	COOLANT		\$ 600.00
5	X	FRONT TYRE RHS		\$ 800.00
		FRONT RIM RHS		\$ 1,485.00

900SN 73231.10
25% 54,123.32
SN 900



Vfx Auto Pte Ltd
24 Chio Ping Road
Singapore 619977
Email: contact@vfxauto.com.sg
Tel: 64552767 Fax: 68628667
UEN / GST REG No.: 201830761R

ESTIMATE

DATE : 24/2/2020
ACC DATE : 20/02/2020
POLICY NO : DMCG18001458

Attention: Motor Claim Department

SHEET NO. 2 OF 2 SHEET

RE: VEHICLE NO: XE4699Y MITSUBISHI / FUSO / CHENG HENG LEE PTE LTD

S/NO	QTY	LABOUR & MISCELLANEOUS	AMOUNT \$
1		To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten affected area, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	2,600.00 2400
2		To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	3,200.00 2000
3		Remove & Refit Front Cabin	1,800.00 900
4		Check & reconnect Wire Harness system & diagnosis fault code	3,200.00 1200
5		Remove & Replace Radiator and Intercooler	400.00 xnn
6		Rejack & Alignment Chassis Frame Member	1,200.00 600
			\$ 12,300.00
GRAND TOTAL			\$ 141,242.33 7100

54923.32

900

7100

62,923.32

415\$50,300 #

25 days