

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305417010
 REGN NO : SHB3780G
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 11.01.2017
 DATE/TIME IN : 15.08.2020 13:25
 ACCIDENT DATE : 15.08.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0103-0579-G	REAR BUMPER	1	1,106.00 20.00 884.80
0002	04-01-0103-0783-G	REAR BUMPER SIDE BRKT RH	1	35.60 20.00 28.48
0003	04-01-0101-0111-G	REAR BUMPER CLIPS	10	22.00 20.00 17.60

SUB-TOTAL : 930.88

JOB NATURE

0000	PB	PANEL BEATING	300.00	280
0001	SP	SPRAYPAINT CHARGE	250.00	200 480

SUB-TOTAL : 550.00

TOTAL : 1,480.88

1382.40

c/s \$1100
 2 days.

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

Taufik 97445449
 WP
 17/8/20 04pm
 c/s posing after repair
 2 days
 tafik@huanb.com
 worksh.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: