



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2169Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DEFORMED	459.40	459.40
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	294.80	-
1	REAR BUMPER REINFORCEMENT BRACKET (RH)	NOT NECESSARY	138.10	-
1	REAR BUMPER CENTRE MOULDING ASSY	DEFORMED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	TO REPAIR SEE LABOUR	155.00	-
1	REAR BUMPER STAY	NOT NECESSARY	138.10	-
1	REAR BUMPER SIDE BRACKET (RH)	NECESSARY	55.80	55.80
1	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER UNDER CENTRE COVER	NOT NECESSARY	225.00	-
1	REAR BUMPER SIDE UNDER (RH)	NOT NECESSARY	108.00	-
1	REAR BUMPER HOOK	NOT NECESSARY	5.40	-
1	REAR BUMPER REFLECTOR LAMP (RH)	CRACKED	31.90	31.90
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
	LESS 20% DISCOUNT		-457.25	-204.07
			1,829.00	816.28
<b><u>NETT ITEMS</u></b>				
1	REAR BUMPER REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
	LESS 10% DISCOUNT		-18.00	-18.00
			162.00	162.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
<b><u>LABOUR</u></b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER CENTRE MOULDING ASSY.		350.00	320.00
	SPRAY PAINTING.		250.00	200.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	30.00
			720.00	550.00

Report Ref No. NS/INC20008630/T1vf3e2

<b>GRAND TOTAL</b>		<b>2,761.00</b>	<b>1,578.28</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>1,578.28</b>

Report Ref No. NS/INC20008630/T1vf3e2



**MOHAMAD TAUFIKH**

**M.MATAI, AMSAE-A**

**Automotive Assessor**



**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.**