

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 31318

Vehicle Insured : SKQ 4970 D
Accident Date : 15-Aug-2020

Date : 18-Aug-2020

Our Ref : 020355 (AIG ASIA) / SANDRA

PAGE : 1

JANNIE SOO KIM LYE MRS.VAN CALCAR-SOO
Singapore

ESTIMATED COST OF REPAIR FOR BMW 318I SEDAN LED NAV(1499cc)-2016 SMR8941H
=====

1 pc rear bumper
1 pc o/s rear bumper side retainer
10 pcs rear bumper clips
1 pc o/s rear door
1 pc o/s rear door weatherstrip

Not without after pain 5 days
11 Sur @ 2200
Resurvey
R 1,178.85
in 65.75
@ S\$ 5.00 50.00
B1/wap 1,273.85
141.40

2,709.85
Less 10% : -270.99

2,438.86

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

800.00 *540*

To apply undersealing

80.00 *30*

To remove door's fittings

100.00 *60*

To putty and respray on affected
portions.

1,000.00 *800*

Total : S\$ 4,418.86
=====

Singapore Dollars Four Thousand Four Hundred
and Eighteen and Cents Eighty Six Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: