

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67

AUTOBAY, SINGAPORE 417883

Hp: 96709191 FAX: 66840767

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Department

Date: 18 August 2020

not Authorized
HAR
1/5 2200
4 days.

**Accident on 14/08/2020 involving vehicles SJ5546Z & SJ29229T
along Yuan Ching Road**

Estimate cost of repair to vehicle SJ5546Z Toyota Vios 1.5A

1 pc.	rear bumper	re / torn	\$ 365.10	✓
1 pc.	rear bumper side retainer rh	un	\$ 48.20	x
1 pc.	rear bumper splash shield rh	De	\$ 87.20	✓
1 pc.	taillamp rh	CR	\$ 345.10	✓
1 pc.	rear fender rh	Red / torn / Bent	\$ 766.50	✓
1 pc.	rear windscreen moulding	un	\$ 98.10	✓
1 pc.	rear shock absorber rh	un	\$ 366.50	x
1 pc.	rear hub bearing	un	\$ 315.10	x
1 pc.	rear sport rm rh	R	\$ 680.00	x
			\$ 3,071.80	
Less 25%			\$ 767.95	
			\$ 2,303.85	

S. Nett Items:

1 set	rear bumper clips	un	\$ 50.00	✓
1 pc.	rear windscreen sealant	un	\$ 50.00	H

Labour Charges:

To check wiring	\$ 50.00	20
To remove & refix reverse sensor	\$ 100.00	50
To remove & refix rear windscreen	\$ 120.00	✓
To remove & refix upholstery	\$ 120.00	80
To spray rust proofing	\$ 100.00	30
To check wheel alignment	\$ 100.00	60
To remove & refix rear undercarriage	\$ 180.00	x
Labour for panel beating, welding & renew parts	\$ 700.00	600
Spray painting	\$ 850.00	500
Total:	\$ 4,723.85	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3-1662
257
1246.50
2796.50
2236