

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
COMFORTDELGRO ENGINEERING PTE LTD		Ref : CC3/QW20008644/T1es3s2		
59 LOYANG DRIVESINGAPORE 508969		Date: 10-09-2020 Code: QW007		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		Veh. Inspected	SHA 4797H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	1	Assign Date	14/08/2020	
2. Vehicle Particulars & Condition				
Make & Mod	el HYUNDAI 140	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHLB41UMHU098291	Colour	BLUE	
Odometer	356009	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Ty	re 205/60 R16	DURATURN	6 mm	
L/H Front Ty		DURATURN	6 mm	
R/H Rear Tyı		DURATURN	6 mm	
L/H Rear Tyr	e 205/60 R16	DURATURN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SE	DAMAGES SEE DETAILS.			
5. General Information				
Accident Da	te 13/08/2020	Inspection Date	14/08/2020	
Survey held	at COMFORTDELGRO ENGINEER	RING PTE LTD		
	59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				