

MFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA4797H

14.08.2020

MAKE

MODEL HYU- I40

CHIANG/ QBE

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER REINFORCEMENT			\$428.40
1	REAR BUMPER UNDER COVER			\$228.00
				\$1,855.60
	25.00% DISCOUNTED TOTAL		1356	\$463.90
			1017	\$1,391.70
1	REVERSE SENSOR			\$135.70
			135.70	\$135.70
	Labour Charge			
	Panel Beating			\$480.00
	Spray Painting Charge			\$300.00
	Remove/refix reverse sensor		510	\$90.00
	Tuff Kote			\$90.00
	TOTAL LABOUR		1662.70	\$960.00
	ESTIMATE TOTAL		1/5 \$1300 2 days	\$2,487.40
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanpak 97195744
 WP 14/8/20 03pm
 2 days Duration
 Complete Repair after repair
 In PM 0/1/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: