

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA4797H

14.08.2020

MAKE

MODEL HYU- I40

CHIANG/ QBE

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER REINFORCEMENT			\$428.40
1	REAR BUMPER UNDER COVER			\$228.00
				\$1,855.60
				\$463.90
	25.00% DISCOUNTED TOTAL			\$1,391.70
1	REVERSE SENSOR			\$135.70
				\$135.70
	Labour Charge			\$480.00
	Panel Beating			\$300.00
	Spray Painting Charge			\$90.00
	Remove/refix reverse sensor			\$90.00
	Tuff Kote			\$960.00
	TOTAL LABOUR			\$960.00
	ESTIMATE TOTAL			\$2,487.40
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tan Jiah 971957461
 WP' 14/8/20 03pm
 2 days Duration
 Complete Repair after repair
 in full 0/1000000.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508089
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 120496

24 Serangoon Road Singapore 556114
7 Dunlop Road Singapore 150001
501 Mahan Industrial Park A Singapore 600201

Date/Time: 14.08.2020 08:34

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO: 30541653

CUSTOMER

MS

CUSTOMER NO

ADDRESS

(R)

(P)

COUNT CARD NO.

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

(O)

REGN NO

SHA4797H

MILEAGE

MAKE :

HYUNDAI

FUEL

E 1/2

MODEL

I-40

DATE/TIME IN

13.08.2020 15:20

YR OF MANU.

25.01.2017

TARGET DATE

CHASSIS CODE

KMHLB41UMHU098291

COMPLETION DATE/TIME

JOB DESCRIPTION


Accident Date: 13.08.2020

NATURE: 3P 13.08.2020

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

No.

SHA4797H

CHIANG

Part Pass

Vehicle No

SHA4797H

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard