

Not Authorized  
11 Pnp @ 1450/-

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5771P**

AAD2008-047

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration:

17 AUG 2020

**SHC 5771P**

VF1ABL15AUC281588

RENAULT

LATITUDE

12.8.2020

**CHINA TAIPING**

10/07/2015

|   | PART                        |
|---|-----------------------------|
| 1 | DOOR PANEL REAR LH          |
| 1 | ROCKER PANEL OUTER LH       |
| 1 | FENDER PANEL REAR LH        |
| 1 | WHEELARCH REAR LH           |
| 1 | BUMPER COVER REAR           |
| 1 | BUMPER LOWER REAR           |
| 1 | BUMPER BRACKET SIDE LH REAR |
| 1 | BUMPER RETAINER LH REAR     |
| 1 | TAILLAMP LH                 |

|          | LIST             |
|----------|------------------|
| \$       | 1 2,844.66       |
| \$       | M.C (R) 1,184.99 |
| \$       | X 1,933.20       |
| \$       | SL 275.40        |
| \$       | SL 561.70        |
| \$       | SL 411.90        |
| \$       | SL 80.80         |
| \$       | SL 54.20         |
| \$       | SL 401.40        |
| TOTAL \$ | 7,748.25         |
| 10% \$   | 774.83           |
| \$       | 6,973.43         |

|      | Special Nett                      |
|------|-----------------------------------|
| 1    | REAR DOOR STICKER '6555-3333'     |
| 1SET | FENDER WHEELARCH REAR LH CLIP     |
| 2    | REAR WINDSCREEN SEALANT           |
| 1    | WINDSCREEN MOULDING               |
| 1    | REAR WINDSCREEN INNER SPONGE SEAL |
| 1    | ROCKER PANEL CLIP                 |
| 1    | REAR LEFT TYRE                    |
| 1    | REAR LEFT TYRE RIM                |
| 1SET | REAR BUMPER CLIP                  |
| 1SET | BUMPER RETAINER CLIP LH RR        |
| 1SET | BUMPER LOWER REAR RIVET           |
| 1SET | BUMPER LOWER REAR CLIP            |

|    |           |      |
|----|-----------|------|
| \$ | na 100.00 | 6050 |
| \$ | na 65.00  |      |
| \$ | na 150.00 |      |
| \$ | na 190.00 |      |
| \$ | na 130.00 |      |
| \$ | na 65.00  |      |
| \$ | SL 300.00 | X    |
| \$ | SL 380.00 | ✓    |
| \$ | na 75.00  | X    |
| \$ | na 65.00  | X    |
| \$ | na 70.00  | X    |
| \$ | na 75.00  | X    |

TOTAL \$ 1,665.00

TOTAL PARTS \$ 8,638.43  
AAD2008-047

# Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5771P

## LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same \$ 1,400.00 4001

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair. \$ 380.00 X

To check steering geometry and computer wheel alignment \$ 220.00 601

To transfer of rear windscreen glass to facilitate bodywork repair. \$ 170.00 X

To transfer of door fittings, attachment and perform water seepage test. \$ 170.00 X

To transfer of tire, rim and on wheel balancing. \$ 170.00 201

To rust-proofing and apply undercoat of the affected areas. \$ 250.00 X

To Check Electrical Lighting Concerned. \$ 170.00 152

To reinstall rear bumper parking sensor. \$ 170.00 X

Putty and spray painting of the affected portion. \$ 1,400.00 881

TOTAL \$ 4,500.00

Over All Total \$ 13,138.43

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: