



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CK VEHICLE RENTAL PTE LTD BLK 1003 EUNOS AVE 8 #01-57 (OFF EUNOS ROAD) SINGAPORE 409498			Ref: CS/TP20008651/Aqf3e2	
			Date: 14/09/2020	
			Code: TP241	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SLV 122Z	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	18/08/2020	
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HARRIER	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTEKB3GH30J001066	Colour	WHITE
	Odometer	58921 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	MICHELIN	6 mm
	L/H Front Tyre	235/55 R18	MICHELIN	6 mm
	R/H Rear Tyre	235/55 R18	MICHELIN	6 mm
	L/H Rear Tyre	235/55 R18	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	31/07/2020	Inspection Date	18/08/2020
	Survey held at	CK VEHICLE RENTAL PTE LTD BLK 1003 EUNOS AVE 8 #01-57 (OFF EUNOS ROAD 2) SINGAPORE 409498		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	