

Not Authored
L / Imp 8

AAD2008-069

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHD 401K

18 AUG 2020

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHD 401K
VF1ABL15AUC283412
RENAULT
LATITUDE
14.8.2020
TOKIO MARINE
17-10-16

| | PART |
|---|-----------------------------------|
| 1 | BUMPER COVER REAR |
| 1 | BUMPER LOWER REAR |
| 1 | BUMPER BRACKET CTR REAR |
| 1 | BUMPER BRACKET SIDE RH REAR |
| 1 | BUMPER RETAINER RH REAR |
| 1 | BUMPER REFLECTOR RH |
| 1 | BUMPER BRACKET SIDE LH REAR |
| 1 | BUMPER RETAINER LH REAR |
| 1 | BUMPER REFLECTOR LH |
| 1 | BUMPER BEAM REAR |
| 1 | BUMPER BEAM BRACKET LH REAR |
| 1 | BUMPER BEAM BRACKET RH REAR |
| 1 | BUMPER BLOCK RH REAR |
| 1 | BUMPER HARNESS REAR |
| 1 | OUTER PANEL REAR (End Panel) |
| 1 | OUTER PANEL REAR (End Panel) TRIM |
| 1 | TAILLAMP RH |
| 1 | TAILLAMP PANEL RH |
| 1 | TAILLAMP LH |
| 1 | TAILLAMP PANEL LH |
| 1 | BOOT REAR |
| 1 | BOOT FINISHER |
| 1 | BOOT WEATHERSTRIP |
| 1 | BOOT REFLECTOR LAMP LH |
| 1 | BOOT REFLECTOR LAMP RH |
| 1 | BOOT BADGE 'RENAULT' |

| | LIST | |
|----|----------------------|---------------|
| \$ | R ₁ | 561.70 ✓ |
| \$ | Dis / CM | 411.90 ✓ |
| \$ | 'CMT | 98.10 ✓ |
| \$ | B ₂ | 82.10 ✓ |
| \$ | Dis | 59.80 ✓ |
| \$ | CM | 16.60 ✓ |
| \$ | SL | 80.80 X |
| \$ | SL | 54.20 X |
| \$ | SL | 16.60 X |
| \$ | R ₁ | 547.80 ✓ |
| \$ | R ₂ | 114.50 ✓ |
| \$ | R ₂ | 114.50 ✓ |
| \$ | SL | 76.50 X |
| \$ | SL | 301.10 X |
| \$ | R ₂ | 745.80 ✓ |
| \$ | mg CM | 404.56 ✓ |
| \$ | mg CM | 401.40 ✓ |
| \$ | R ₂ | 401.40 ✓ |
| \$ | mg CM | 401.40 ✓ |
| \$ | R | 401.40 X |
| \$ | R ₁ | 1,677.20 ✓ |
| \$ | SL | 344.70 X |
| \$ | Dis / R ₂ | 178.20 50% SL |
| \$ | SL | 277.70 X |
| \$ | CM | 277.70 ✓ |
| \$ | R ₂ | 82.40 ✓ |

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 401K**AAD2008-069**

- 1 BOOT BADGE
- 1 BOOT STRUT LH
- 1 BOOT TRIM BOARD
- 1 BOOT STRUT RH
- 1 BOOT HINGE LH
- 1 BOOT HINGE RH
- 1 BOOT LOCK
- 2 BOOT RUBBER PLUG
- 2 LICENCE PLATE LAMP
- 1 BOOT SWITCH
- 1 EXHAUST REAR
- 1 EXHAUST CAP REAR
- 1 REAR RH FENDER PANEL
- 1 WHEELARCH REAR RH
- 1 FENDER PANEL INNER TRIM REAR RH
- 1 SPARE WHEEL PANEL
- 1 SPARE WHEEL PANEL TRIM
- 1 SPARE WHEEL PANEL BRACKET RH
- 1 SPARE TYRE BOARD
- 1 CHASSIS PANEL REAR RH
- 1 FENDER PANEL INNER REAR RH
- 1 FENDER INNER BOARD RH
- 1 WHEEL HOUSING PANEL REAR RH
- 1 DOOR PANEL REAR RH
- 1 DOOR LOCK REAR RH
- 1 KNUCKLE ARM REAR RH
- 1 WHEEL HUB NUT
- 1 WHEEL HUB CAP
- 1 ABS SENSOR REAR RH
- 1 REAR AXLE
- 1 AXLE SPRING ARM RH
- 1 UPPER CONTROL ARM REAR RH
- 1 ABSORBER REAR
- 1 ABSORBER MOUNTING REAR

| | | | |
|----|--------------|----------|-----|
| \$ | <i>Mu</i> | 95.80 | ✓ |
| \$ | <i>Sm</i> | 145.10 | } X |
| \$ | <i>Sm</i> | 611.00 | |
| \$ | <i>Sm</i> | 145.10 | |
| \$ | <i>R</i> | 254.20 | |
| \$ | <i>R</i> | 254.20 | |
| \$ | <i>R</i> | 246.60 | } |
| \$ | <i>Sm</i> | 139.30 | |
| \$ | <i>Sm</i> | 26.30 | |
| \$ | <i>Sm</i> | 113.00 | } |
| \$ | <i>Ry</i> | 5,263.60 | |
| \$ | <i>Nu</i> | 125.40 | ✓ |
| \$ | <i>Bu</i> | 1,933.20 | ✓ |
| \$ | <i>Dir</i> | 275.40 | ✓ |
| \$ | <i>R</i> | 671.45 | X |
| \$ | <i>Atlan</i> | 1,229.40 | ✓ |
| \$ | <i>Sm</i> | 612.21 | X |
| \$ | <i>R</i> | 69.20 | X |
| \$ | <i>Sm</i> | 680.90 | X |
| \$ | <i>R</i> | 2,192.40 | } X |
| \$ | <i>R</i> | 1,241.60 | |
| \$ | <i>Sm</i> | 561.40 | |
| \$ | <i>R</i> | 4,682.09 | |
| \$ | <i>R</i> | 2,844.66 | |
| \$ | <i>R</i> | 467.30 | |
| \$ | <i>Sm</i> | 472.10 | |
| \$ | <i>Sm</i> | 41.80 | |
| \$ | <i>Sm</i> | 30.50 | |
| \$ | <i>Sm</i> | 190.50 | |
| \$ | <i>Sm</i> | 3,469.00 | |
| \$ | <i>Sm</i> | 220.60 | } |
| \$ | <i>Sm</i> | 543.50 | |
| \$ | <i>Sm</i> | 217.30 | |
| \$ | <i>Sm</i> | 49.40 | |

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6257 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SND 401K

AAD2008-069

- 1 STABILIZER BAR REAR
- 1 STABILIZER LINK REAR
- 1 SUBFRAME ARM REAR RH
- 1 ROD - LONG REAR RH
- 1 KNUCKLE HUB & BEARING RH
- 1 EXTENSION- REAR RH SIDE MEMBER

| | | | | |
|--------------|----|------------------|---|---|
| \$ | Sn | 427.90 | } | X |
| \$ | Sn | 55.20 | | |
| \$ | Sn | 198.33 | | |
| \$ | Sn | 120.16 | | |
| \$ | Sn | 272.30 | | |
| \$ | Sn | 233.20 | | |
| TOTAL | \$ | 39,552.66 | | |
| 10% | \$ | 3,955.27 | | |
| | \$ | 35,597.39 | | |

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1SET BUMPER BRACKET CTR CLIP
- 1SET BUMPER BRACKET SIDE CLIP RH RR
- 1SET BUMPER RETAINER RH CLIP RR
- 1SET BUMPER BRACKET SIDE CLIP LH RR
- 1SET BUMPER RETAINER CLIP LH RR
- 1SET BUMPER LOWER REAR RIVET
- 1SET BUMPER LOWER REAR CLIP
- 1 BOOT STICKER "Trans-cab"
- 1 BOOT STICKER "6555-3333"
- 1SET BOOT FINISHER CLIP
- 1 TAILLAMP CLIP LH
- 1 TAILLAMP CLIP RH
- 1 Rear Bumper Protector
- 1 REAR LICENCE PLATE WITH HOLDER
- 1 EXHAUST MOUNTING
- 1 FENDER INNER TRIM CLIP RH
- 1SET FENDER WHEELARCH REAR RH CLIP
- 2 REAR WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 REAR WINDSCREEN INNER SPONGE SEAL
- 2 SEAM SEALANT

| | | | |
|----|------|--------|--------|
| \$ | Shay | 700.00 | 400.00 |
| \$ | na | 75.00 | ✓ |
| \$ | na | 65.00 | } X |
| \$ | na | 60.00 | |
| \$ | na | 50.00 | |
| \$ | na | 60.00 | |
| \$ | na | 50.00 | |
| \$ | na | 70.00 | } ✓ |
| \$ | na | 75.00 | |
| \$ | na | 80.00 | 300.00 |
| \$ | na | 80.00 | 300.00 |
| \$ | na | 55.00 | X |
| \$ | na | 40.00 | 5.00 |
| \$ | na | 40.00 | 5.00 |
| \$ | na | 180.00 | 300.00 |
| \$ | na | 140.00 | X |
| \$ | na | 90.00 | X |
| \$ | na | 60.00 | ✓ |
| \$ | na | 65.00 | X |
| \$ | na | 150.00 | 400.00 |
| \$ | na | 200.00 | X |
| \$ | na | 130.00 | 300.00 |
| \$ | na | 190.00 | X |

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD 401K

AAD2008-069

- 1 REAR RENAULT TYRE 215/60/16
- 1 REAR RENAULT TYRE RIM
- 1 SPARE TYRE
- 1 SET END PANEL TRIM CLIP
- 1 SPARE TYRE 215/60/16
- 1 SPARE TYRE RIM
- 1 EXHAUST BRACKET
- 1 EXHAUST SCREW
- 1 EXHAUST CLAMP
- 1 REAR DOOR STICKER "6555-3333"
- 1 BOOT TRIM BOARD CLIP

| | | | | |
|--------------|-----------|-----------------|---|---|
| \$ | PH | 330.00 | } | X |
| \$ | PH | 380.00 | | |
| \$ | PH | 330.00 | | |
| \$ | NN | 55.00 | | |
| \$ | PH | 330.00 | | |
| \$ | PH | 380.00 | | |
| \$ | PH | 60.00 | | |
| \$ | PH | 50.00 | | |
| \$ | PH | 68.80 | | |
| \$ | NN | 100.00 | | |
| \$ | NN | 65.00 | | |
| TOTAL | \$ | 4,853.80 | | |

TOTAL PARTS \$ 40,451.19

LABOUR

| | | | | |
|--|----|----|--------|------|
| To check steering geometry and computer wheel alignment | \$ | NN | 220.00 | X |
| To drop rear exhaust box, renew the same, to repair and realign rear and centre exhaust pipe. | \$ | | 380.00 | 801 |
| To transfer of bootlid fittings, attachments and perform water seepage test. | \$ | | 170.00 | 601 |
| To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair. | \$ | | 380.00 | 1201 |
| To transfer of rear bumper fittings, attachment and perform water seepage test. | \$ | NN | 170.00 | X |
| To transfer of rear end panel fittings, attachment and perform water seepage test. | \$ | NN | 380.00 | X |
| Towing Fees | \$ | | 150.00 | 501 |

Trans-cab Auto Services Pte Ltd

AAD2008-069

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 401K

| | | | |
|---|----|-----------|------|
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 2,800.00 | 2000 |
| To transfer of tire, rim and on wheel balancing. | \$ | nn 170.00 | X |
| To transfer of rear fender fittings, attachment and perform water seepage test. | \$ | nn 170.00 | X |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair. | \$ | 380.00 | 2500 |
| To transfer of rear windscreen glass to facilitate bodywork repair. | \$ | 170.00 | 1200 |
| To transfer of door fittings, attachment and perform water seepage test. | \$ | nn 170.00 | X |
| To Rust-Proofing and apply undercoat Of The Affected Areas. | \$ | 250.00 | 1200 |
| To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack. | \$ | 380.00 | X |
| To transfer of rear luggage floor panel fittings, attachment and perform water seepage test. | \$ | 380.00 | X |
| Putty and spray painting of the affected portion. | \$ | 2,800.00 | 1100 |
| To dismantle and refit rear undercarriage parts, final checking and testing. | \$ | 380.00 | 2200 |
| To dismantle and refit rear axle assy, remove and renewal of parts, final checking and testing. | \$ | nn 380.00 | X |

Trans-cab Auto Services Pte Ltd

AAD2008-069

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 401K

| | | | |
|--|----|----------------------|-----|
| To reinstall rear bumper parking sensor. | \$ | 170.00 | 602 |
| To Check Electrical Lighting Concerned. | \$ | 170.00 | 201 |
| To repair and realign rear exhaust pipe. | \$ | <i>Repair</i> 170.00 | X |
| To check ABS and brake efficiency, final checking and testing. | \$ | <i>un</i> 380.00 | X |
| TOTAL | \$ | 11,170.00 | |
| Over All Total | \$ | 51,621.19 | |

LUMP SUM (REPAIR DAY)

~~25 DAYS~~

14 days

For Official Use

Prepared By : _____
(Accident Dept)Verify By : _____
(Accident Workshop)Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 17/08/2020 10:08
 Date Of Accident 14/08/2020 14:50
 Exact Location Of Accident CTE SLIP ROAD TOWARDS PIE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD401K
Insured/Policyholder
 Name Of Registered Owner TRANS-CAB SERVICES PTE LTD
 Co Reg No 2XXXXX878K
 Email Address CLAIMS@TRANSCAB.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-62866666

Vehicle Particulars

Manufacturer RENAULT
 Model LATITUDE-2.0 L (A)
 Exact Purpose for which vehicle was being used at time of accident HIRE AND REWARD
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
 Type Of Coverage THIRD PARTY
 Fleet Policy YES
 Policy Number VFX/P2348706
 Cover Note Number

Driver

Name of Driver CHAN YEW WAH PETER
 NRIC No SXXXX105A
 Date Of Birth 24/01/1954
 Occupation OUTDOOR
 Date Of Driving Pass 05/01/1980
 Driving Experience 40 YEARS AND 7 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-98173493
 Fax Number
 Contact Number
 Email Address NOEMAIL