

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 45615

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0574/2020/NS
Date	:	17-Aug-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Hari Jaya Singh Kiran Kumar
Address	:	9 Rivervale Crescent #06-22 Singapore 545086
Telephone	:	HP +65 83826281
Type of Claim	:	Own Damage Claim
Policy No.	:	1700058585-02
Vehicle No	:	SLS 6931 G
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	Sep-17
Engine No	:	CHZ 531220
Chassis No	:	WAUZZZ8V5J1013790
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	15-Aug-20
Place of Accident	:	Rivervale Crescent Parking Lot

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLS 6931 G

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00 ✓	✓
2	to renew rear windscreen and lhs rear 1/4 glass to facilitate fender renewal.	S/N \$	600.00 ✓	✓
3	To install solar film for rear windscreen and lhs rear 1/4 glass.	S/N \$	400.00 ✓	✓
4	To carry out water seepage test for rear windscreen. <i>+ 1/4 glass</i>	S/N \$	200.00 <i>150.</i>	✓
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00 ✓	✓
6	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, kuggage compartment trims. Dislodge roof liner and disenqage curtain airbaq etc.	S/N \$	1,400.00 ✓	✓
7	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	280.00 ✓	✓
8	To dismantle rear bumper, rear lid and lhs rear door. To renew lhs rear door. Cut out and weld lhs rear fender. Re-organise crash management components. Reinstall all parts removed.	\$	6,300.00 <i>3500</i>	✓
9	To respray lhs rear fender, lhs rear door, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$	4,900.00 <i>2750.</i>	✓
10	To renew lhs rear rim and carry out wheel alignment.	S/N \$	280.00 ✓	✓
11	To carry out diagnostic check.	S/N \$	192.00 ✓	✓
TOTAL LABOUR CHARGES			: <u>\$ 16,232.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 6931 G

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR FENDER - LH <i>Dented</i>	\$ 2,305.00 ✓	1844
2	REAR WINDSCREEN <i>crack</i>	\$ 805.00 ✓	643.60
3	SIDE WINDOW - LH <i>scr</i>	\$ 563.00 ✓	450.40
4	WHEEL HOUSING LINER <i>Not nec</i>	\$ 237.00 + X	
5	REAR DOOR - LH <i>Dented</i>	\$ 2,494.00 ✓	1995.20
6	REAR OUTER DOOR SEAL - LH <i>scr</i>	NEC \$ 159.00 ✓	126.80
7	BONDING AGENT <i>Not nec</i>	NEC \$ 47.00 ? X	
8	CLEANING SOLUTION <i>Not nec</i>	NEC \$ 65.00 ? X	
9	REAR DOOR ATTACHMENT PARTS <i>Not nec</i>	\$ 127.00 ? X	
10	REAR DOOR CATCH <i>not nec</i>	\$ 93.00 + X	
11	REAR ALUMINIUM RIM - LH <i>scr</i>	\$ 699.00 ✓	558.80
12	REAR WINDSCREEN SEALANT <i>scr</i>	S/N \$ 200.00 ✓	200
13	1/4 GLASS SEALANT <i>free</i>	S/N \$ 100.00 ✓	100
14	METAL FILLER POWDER <i>free</i>	S/N \$ 280.00 ✓	280
15	STONE CHIP <i>free</i>	S/N \$ 180.00 ✓	180
16	CAVITY WAX <i>free</i>	S/N \$ 140.00 ✓	140
17	ACRYLIC SEALANT <i>free</i>	S/N \$ 180.00 ✓	180
18	SUNDRIES <i>Nec.</i>	\$ 400.00 ?	11.28

TOTAL SPARE PARTS CHARGES

: \$ 9,074.00

TOTAL LABOUR CHARGES

: \$ 16,232.00

GRAND TOTAL

: \$ 25,306.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian L
Surveyed Date : 19/08/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 13 Days ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 45615

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0574/2020/NS
Date : 17-Aug-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

13 days - ok - Jy - 16 Dec 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Hari Jaya Singh Kiran Kumar
Address : 9 Rivervale Crescent
#06-22
Singapore 545086
Telephone : HP + 65 83826281
Type of Claim : Own Damage Claim
Policy No. : 1700058585-02
Vehicle No : **SLS 6931 G**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Sep-17
Engine No : CHZ 531220
Chassis No : WAUZZZ8V5J1013790
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Aug-20
Place of Accident : Rivervale Crescent Parking Lot

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLS 6931 G

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00 \$	280.00
2	to renew rear windscreen and lhs rear 1/4 glass to facilitate fender renewal.	S/N \$	600.00 \$	600.00
3	To install solar film for rear windscreen and lhs rear 1/4	S/N \$	400.00 \$	400.00
4	To carry out water seepage test for rear windscreen.	S/N \$	200.00 \$	150.00
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and	S/N \$	1,400.00 \$	1,400.00
6	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, kuggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00 \$	1,400.00
7	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	280.00 \$	280.00
8	To dismantle rear bumper, rear lid and lhs rear door. To renew lhs rear door. Cut out and weld lhs rear fender. Re-organise crash management components. Reinstall all	\$	6,300.00 \$	3,500.00
9	To respray lhs rear fender, lhs rear door, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint	\$	4,900.00 \$	2,750.00
10	To renew lhs rear rim and carry out wheel alignment.	S/N \$	280.00 \$	280.00
11	To carry out diagnostic check.	S/N \$	192.00 \$	192.00
TOTAL LABOUR CHARGES		:	\$ 16,232.00	\$ 11,232.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 6931 G

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR FENDER - LH	\$ 2,305.00	\$ 1,844.00
2	REAR WINDSCREEN	\$ 805.00	\$ 643.60
3	SIDE WINDOW - LH	\$ 563.00	\$ 450.40
4	WHEEL HOUSING LINER	\$ 237.00	
5	REAR DOOR - LH	\$ 2,494.00	\$ 1,995.20
6	REAR OUTER DOOR SEAL - LH	NEC \$ 159.00	\$ 126.80
7	BONDING AGENT	NEC \$ 47.00	
8	CLEANING SOLUTION	NEC \$ 65.00	
9	REAR DOOR ATTACHMENT PARTS	\$ 127.00	
10	REAR DOOR CATCH	\$ 93.00	
11	REAR ALUMINIUM RIM - LH	\$ 699.00	\$ 558.80
12	REAR WINDSCREEN SEALANT	S/N \$ 200.00	\$ 200.00
13	1/4 GLASS SEALANT	S/N \$ 100.00	\$ 100.00
14	METAL FILLER POWDER	S/N \$ 280.00	\$ 280.00
15	STONE CHIP	S/N \$ 180.00	\$ 180.00
16	CAVITY WAX	S/N \$ 140.00	\$ 140.00
17	ACRYLIC SEALANT	S/N \$ 180.00	\$ 180.00
18	SUNDRIES	\$ 400.00	\$ 11.28
TOTAL SPARE PARTS CHARGES		: \$ 9,074.00	\$ 6,710.08
TOTAL LABOUR CHARGES		: \$ 16,232.00	\$ 11,232.00
GRAND TOTAL		: \$ 25,306.00	\$ 17,942.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.