

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 45615**

## Telefax

<b>Estimate</b>	:	Accident Repairs
<b>Workshop</b>	:	Ubi Road 1
<b>Contact No</b>	:	6366 2323
<b>Fax No</b>	:	6841 1183
<b>Reference</b>	:	PA/OD/0574/2020/NS
<b>Date</b>	:	17-Aug-20

**Vehicle NOT IN workshop. Kindly arrange for survey.**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

<b>Owner's Name</b>	:	Mr Hari Jaya Singh Kiran Kumar
<b>Address</b>	:	9 Rivervale Crescent #06-22 Singapore 545086
<b>Telephone</b>	:	HP +65 83826281
<b>Type of Claim</b>	:	Own Damage Claim
<b>Policy No.</b>	:	1700058585-02
<b>Vehicle No</b>	:	<b>SLS 6931 G</b>
<b>Model Code</b>	:	Audi A3 Sedan 1.0 TFSI 8V
<b>Model / Year</b>	:	Sep-17
<b>Engine No</b>	:	CHZ 531220
<b>Chassis No</b>	:	WAUZZZ8V5J1013790
<b>Mileage</b>	:	-
<b>Date In</b>	:	-
<b>Estimated By</b>	:	Johnny Boo / Allan Wu
<b>Accident Date</b>	:	15-Aug-20
<b>Place of Accident</b>	:	Rivervale Crescent Parking Lot

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SLS 6931 G

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00	✓ ✗
2	to renew rear windscreen and lhs rear 1/4 glass to facilitate fender renewal.	S/N \$	600.00	✓ ✓
3	To install solar film for rear windscreen and lhs rear 1/4 glass.	S/N \$	400.00	✓ ✓
4	To carry out water seepage test for rear windscreen. + 1/4 glass	S/N \$	<del>200.00</del> 150.	✓ ✓
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	✓ ✓
6	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, kuggage compartment trims. Dislodge roof liner and disenqage curtain airbag etc.	S/N \$	1,400.00	✓ ✓
7	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	280.00	✓ ✓
8	To dismantle rear bumper, rear lid and lhs rear door. To renew lhs rear door. Cut out and weld lhs rear fender. Re-organise crash managment components. Reinstall all parts removed.	\$	<del>6,300.00</del> 3500	✓
9	To respray lhs rear fender, lhs rear door, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$	<del>4,900.00</del> 2750	✓
10	To renew lhs rear rim and carry out wheel alignment.	S/N \$	280.00	✓ ✓
11	To carry out diagnostic check.	S/N \$	192.00	✓ ✓
<b>TOTAL LABOUR CHARGES</b>			<b>: \$ 16,232.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLS 6931 G

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR FENDER - LH <i>Dented</i>	\$ 2,305.00 ✓	1844
2	REAR WINDSCREEN <i>Alone</i>	\$ 805.00 ✓	643.60
3	SIDE WINDOW - LH <i>Alone</i>	\$ 563.00 ✓	450.40
4	WHEEL HOUSING LINER <i>Not nec</i>	\$ 237.00 + X	
5	REAR DOOR - LH <i>Dented</i>	\$ 2,494.00 ✓	1995.20
6	REAR OUTER DOOR SEAL - LH <i>Alone</i>	NEC \$ 159.00 ✓	126.80
7	BONDING AGENT <i>Not nec</i>	NEC \$ 47.00 ? X	
8	CLEANING SOLUTION <i>Not nec</i>	NEC \$ 65.00 ? X	
9	REAR DOOR ATTACHMENT PARTS <i>Not nec</i>	\$ 127.00 ? X	
10	REAR DOOR CATCH <i>Not nec</i>	\$ 93.00 + X	
11	REAR ALUMINIUM RIM - LH <i>lit</i>	\$ 699.00 ✓	558.80
12	REAR WINDSCREEN SEALANT <i>Alone</i>	S/N \$ 200.00 ✓	200
13	1/4 GLASS SEALANT <i>Free</i>	S/N \$ 100.00 ✓	100
14	METAL FILLER POWDER <i>Free</i>	S/N \$ 280.00 ✓	280
15	STONE CHIP <i>Free</i>	S/N \$ 180.00 ✓	180
16	CAVITY WAX <i>Free</i>	S/N \$ 140.00 ✓	140
17	ACRYLIC SEALANT <i>Free</i>	S/N \$ 180.00 ✓	180
18	SUNDRIES <i>Nec</i>	\$ 400.00 ?	11.28
<b>TOTAL SPARE PARTS CHARGES</b>		<b>: \$ 9,074.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 16,232.00</b>	
<b>GRAND TOTAL</b>		<b>: \$ 25,306.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name

: Adrian L

Surveyed Date

: 19/08/20

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 13 Days ✓

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Please Note

- : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant