

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 36787

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0415/2020/NS
Date : 8-Jun-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SMP 1660 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Rasul,

5 days - ok - Jy -03 Nov 20

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Ms Chan Ruo Jun
Address : Blk 420 Choa Chu Kang Ave 4
#10-316
Singapore 680420
Telephone : HP +65 97738647
Type of Claim : Own Policy Claims
Policy No. : 1900130169
Vehicle No : **SLR 4875 D**
Model Code : Audi A3 SEDAN 1.0 TFSI S TRONIC
Model / Year : Aug-17
Engine No : CHZ 508633
Chassis No : WAUZZZ8V4J1005325
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Jun-20
Place of Accident : Choa Chu Kang Way

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLR 4875 D

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy. S/N \$	360.00	\$ 360.00
2	To remove and renew front bumper, lhs front fender and lhs headlight. Re-organise rear crash management components, reinstall all parts removed. \$	2,450.00	\$ 1,250.00
3	To respray front bumper and lhs front fender. \$	2,000.00	\$ 1,100.00
4	To renew lhs front rim and carry out wheel alignment. S/N \$	280.00	
5	To carry out diagnostic check. S/N \$	192.00	\$ 192.00
SUB TOTAL LABOUR CHARGES		: \$ 5,282.00	\$ 2,902.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 4875 D

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,894.00	
2	FRONT BUMPER FIXING PARTS	\$ 176.00	
3	FRONT BUMPER GUIDE SECTION - LH	\$ 36.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 505.00	
5	FRONT BUMPER CLOSING ELEMENT - LH	\$ 280.00	
6	FRONT BUMPER COVER TRIM - LH	\$ 153.00	
7	WHEEL HOUSING LINER ADAPTER - LH	\$ 36.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 177.00	
9	FRONT FENDER - LH	\$ 802.00	\$ 641.60
10	FRONT FENDER ATTACHMENT PARTS	\$ 68.00	
11	FRONT FENDER BRACKET - LH	\$ 36.00	
12	FRONT FENDER BRACE	\$ 90.00	
13	WHEEL HOUSING LINER SEAL - LH	\$ 32.00	
14	WHEEL HOUSING LINER - LH	\$ 160.00	
15	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 84.00	
16	LED HEADLIGHT - LH	\$ 5,193.00	\$ 4,154.40
17	LIFT CYLINDER	\$ 134.00	
18	FRONT ALUMINIUM RIM - LH	\$ 666.00	
19	SUNDRIES	\$ 300.00	\$ 54.40
TOTAL SPARE PARTS CHARGES		\$ 10,822.00	\$ 4,850.40
TOTAL LABOUR CHARGES		\$ 5,282.00	\$ 2,902.00
GRAND TOTAL		\$ 16,104.00	\$ 7,752.40

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant