

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 36787

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0415/2020/NS
Date : 8-Jun-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SMP 1660 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Rasul,
5 days - ok - Jy -03 Nov 20

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Ms Chan Ruo Jun
Address : Blk 420 Choa Chu Kang Ave 4
#10-316
Singapore 680420
Telephone : HP +65 97738647
Type of Claim : Own Policy Claims
Policy No. : 1900130169
Vehicle No : **SLR 4875 D**
Model Code : Audi A3 SEDAN 1.0 TFSI S TRONIC
Model / Year : Aug-17
Engine No : CHZ 508633
Chassis No : WAUZZZ8V4J1005325
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Jun-20
Place of Accident : Choa Chu Kang Way

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 4875 D

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 1,894.00	
2	FRONT BUMPER FIXING PARTS	\$ 176.00	
3	FRONT BUMPER GUIDE SECTION - LH	\$ 36.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 505.00	
5	FRONT BUMPER CLOSING ELEMENT - LH	\$ 280.00	
6	FRONT BUMPER COVER TRIM - LH	\$ 153.00	
7	WHEEL HOUSING LINER ADAPTER - LH	\$ 36.00	
8	FRONT BUMPER AIR GUIDE GRILLE - LH	\$ 177.00	
9	FRONT FENDER - LH	\$ 802.00	\$ 641.60
10	FRONT FENDER ATTACHMENT PARTS	\$ 68.00	
11	FRONT FENDER BRACKET - LH	\$ 36.00	
12	FRONT FENDER BRACE	\$ 90.00	
13	WHEEL HOUSING LINER SEAL - LH	\$ 32.00	
14	WHEEL HOUSING LINER - LH	\$ 160.00	
15	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 84.00	
16	LED HEADLIGHT - LH	\$ 5,193.00	\$ 4,154.40
17	LIFT CYLINDER	\$ 134.00	
18	FRONT ALUMINIUM RIM - LH	\$ 666.00	
19	SUNDRIES	\$ 300.00	\$ 54.40
TOTAL SPARE PARTS CHARGES		: \$ 10,822.00	\$ 4,850.40
TOTAL LABOUR CHARGES		: \$ 5,282.00	\$ 2,542.00
GRAND TOTAL		: \$ 16,104.00	\$ 7,392.40

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLR 4875 D

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy. S/N \$	360.00	
2	To remove and renew front bumper, lhs front fender and lhs headlight. Re-organise rear crash management components, reinstall all parts removed. \$	2,450.00	\$ 1,250.00
3	To respray front bumper and lhs front fender. \$	2,000.00	\$ 1,100.00
4	To renew lhs front rim and carry out wheel alignment. S/N \$	280.00	
5	To carry out diagnostic check. S/N \$	192.00	\$ 192.00
SUB TOTAL LABOUR CHARGES		: \$ 5,282.00	\$ 2,542.00