

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 44952

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0557/2020/NS
Date : 12-Aug-20

Vehicle IN workshop. Please arrange for survey

Your insured vehicle no : GZ 9393 L

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Udai Singh
Address : 36 Ewe Boon Road
#08-01
Singapore 259333
Telephone : (Hp) +65 98717677
Type of Claim : Own Damage Claim
Policy No. : 1800001279-02
Vehicle No : **SKX 5405 B**
Model Code : Audi A5 SB 1.8 TFSI MU 8T
Model / Year : Dec-15
Engine No : CJE 102930
Chassis No : WAUZZZ8T2FA059034
Mileage : 80954
Date In : 11-Aug-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-Aug-20
Place of Accident : Bukit Timah Road Before Six Avenue Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 5405 B

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00 /	
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$	280.00 /	
3	To renew rear windscreen to facilitate rear lid renewal.	S/N \$	480.00 /	
4	To install solar film for rear windscreen.	S/N \$	400.00 ?Xm	
5	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$	480.00 /	
6	To dismantle and renew rear bumper and rear lid. To cut out and reweld rear end panelling outer and inner. Re-organise rear crash management components. Reinstall all parts removed.	\$	4,800.00 2,500 /	
7	To respray rear bumper, rear lid, hinges, lhs rear fender and end panelling. To carry out joint sealer works and stone chip treatment.	\$	4,500.00 2200 /	
8	To renew lhs rear exhaust silencer. To align to position.	S/N \$	480.00 ?Xm	
9	To carry out water seepage test on rear windscreen.	S/N \$	200.00 / /	
10	To carry out diagnostic check.	S/N \$	192.00 / /	
TOTAL LABOUR CHARGES			: \$ 12,092.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 5405 B

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>de</i>	\$	2,569.00 <i>2055.20</i>
2	REAR BUMPER FIXING PARTS <i>? Xnn</i>	\$	225.00
3	REAR BUMPER CARRIER <i>? bt</i>	\$	636.00 <i>508.40</i>
4	REAR BUMPER BRACKET HOLDER - LH / RH <i>? bt</i>	2 \$	440.00 <i>352.00</i>
5	REAR BUMPER SPOILER <i>su</i>	\$	273.00 <i>218.00</i>
6	REAR BUMPER GUIDE SECTION - LH / RH UPPER <i>? Xsu</i>	2 \$	38.00
7	REAR PARKING AID SENSOR - INNER / OUTER <i>mi / 1 pc</i>		TBC <i>200</i>
8	REAR BUMPER WIRING SET <i>? Xsu</i>	\$	510.00
9	REAR LID <i>bt</i>	\$	2,608.00 <i>2086.40</i>
10	REAR LID ATTACHMENT PARTS <i>? Xsu</i>	\$	113.00
11	REAR LID HINGE - LH / RH <i>bt</i>	2 \$	452.00 <i>361.60</i>
12	REAR LID FLAP GASKET <i>nee</i>	\$	222.00 <i>177.60</i>
13	REAR LID FLAP GASKET - UPPER REAR <i>? Xsu</i>	\$	100.00
14	REAR LID STRIKER PLATE <i>? Xsu</i>	\$	122.00
15	REAR LID LOCK <i>? bt</i>	\$	169.00 <i>135.20</i>
16	LID LOCK PUSH BUTTON <i>? de</i>	\$	172.00 <i>137.60</i>
17	PACKING ADHESIVE <i>nee</i>	\$	18.00 <i>14.40</i>
18	GAS FILLED STRUT <i>Xsu</i>	2 \$	235.00
19	AUDI EMBLEM <i>nee</i>	\$	122.00 <i>97.60</i>
20	A5 INSCRIPTION <i>nee</i>	\$	95.00 <i>75.36</i>
SUB TOTAL SPARE PARTS CHARGES		:	\$ <u>9,119.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 5405 B

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	TFSI INSCRIPTION <i>nee</i> ✓	\$ 95.00	75.36
22	REAR WINDSCREEN <i>nee</i> ✓ <i>photo?</i> ✓	\$ 1,108.00	886.40
23	PRIMER <i>nee</i> ✓	\$ 19.00	14.96
24	LED TAIL LIGHT - LH / RH <i>cal</i> ✓ <i>1pc</i> ✗	\$ 2,450.00	980.00
25	LED TAIL LIGHT - LH / RH <i>cal</i> ✓ <i>1pc</i> ✗	\$ 1,716.00	686.00
26	LED LICENSE PLATE LIGHT <i>con</i> ✓ <i>1pc</i> ✗	\$ 113.00	45.12
27	ADDITIONAL BRAKE LIGHT <i>nee</i> ✓	\$ 446.00	356.40
28	REAR CROSS PANEL - OUTER <i>bt</i> ✓	\$ 519.00	415.20
29	CROSS PANEL - LOWER <i>bt</i> ✓	\$ 859.00	687.20
30	CROSS PANEL REINFORCEMENT - INNER <i>bt</i> ✓	\$ 668.00	534.40
31	REAR CROSS PANEL TRIM <i>con</i> ✓	\$ 175.00	140.00
32	LUGGAGE COMPARTMENT FLOOR <i>xscr</i>	\$ 701.00	
33	REAR LID TRIM PANEL <i>scr</i> ✓	\$ 478.00	382.00
34	REAR SILENCER - LH <i>? xscr</i>	\$ 824.00	
35	REAR SILENCER DUAL CLIP <i>? xscr</i>	\$ 57.00	
36	REAR SILENCER BRACKET <i>? xscr</i>	\$ 57.00	
37	REAR NO PLATE <i>bt</i> ✓	S/N \$ 60.00	✓
38	REAR WINDSCREEN SEALANT <i>nee</i> ✓	S/N \$ 200.00	✓
39	STONE CHIP <i>nee</i> ✓	S/N \$ 180.00	✓
40	CAVITY WAX <i>nee</i> ✓	S/N \$ 140.00	✓
41	ACRYLIC SEALANT <i>nee</i> ✓	S/N \$ 180.00	✓
42	SUNDRIES <i>? nee</i> ✓	\$ 400.00	86.08
TOTAL SPARE PARTS CHARGES		: \$ 20,564.00	
TOTAL LABOUR CHARGES		: \$ 12,092.00	
GRAND TOTAL		: \$ 32,656.00	36,850.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Rasul - HP 900 6068
Surveyed Date : 19/08/2020 @ 1000h
Authorised Date :
Excess Cost : 12 to days
Liability : EXCESS: TBA
Remarks : REVERT
Resur before paint

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/TP/0557/2020/NS

20-Aug-20

Glory Tan

1 OF 1

SKX 5405 B

Audi A5 SB 1.8 TFSI MU 8T

Quantity	Description	Unit Price	Amount
Parts			
1	Rear lid guard plate	\$ 61.00	de 48.72
2	Rear lid cover for lock	\$ 8.00	de 6.00
3	Cable holder for rear lid trim panel	\$ 45.00	de 35.52
Labours			
1	To repair rhs tail lamp panel and lhs tail lamp panel.	\$ 1,200.00	1000
2	To respray rhs tail lamp panel and lhs tail lamp panel. <i>RM side fender</i>	\$ 2,000.00	1650
TOTAL		\$ 3,314.00	

add + 2 days for repair
21/8/20.

For Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0557/2020/NS 25-Aug-20 Glory Tan 1 OF 1 SKX 5405 B Audi A5 SB 1.8 TFSI MU 8T
Quantity	Description	Unit Price	Amount
<u>Labours</u> 1	To dislodge and reinstall roof liner to facilitate the renewal of rear lid hinges.	s/n \$ 280.00	
TOTAL		\$ 280.00	

For Premium Automobiles Pte Ltd

Authorised Signature

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: