

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 44952

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0557/2020/NS
Date : 12-Aug-20

Vehicle IN workshop. Please arrange for survey

Your insured vehicle no : GZ 9393 L

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

12 days - ok - Jy - 02 Dec 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Udai Singh
Address : 36 Ewe Boon Road
#08-01
Singapore 259333
Telephone : (Hp) +65 98717677
Type of Claim : Own Damage Claim
Policy No. : 1800001279-02
Vehicle No : **SKX 5405 B**
Model Code : Audi A5 SB 1.8 TFSI MU 8T
Model / Year : Dec-15
Engine No : CJE 102930
Chassis No : WAUZZZ8T2FA059034
Mileage : 80954
Date In : 11-Aug-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 09-Aug-20
Place of Accident : Bukit Timah Road Before Six Avenue Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 5405 B

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00	\$ 280.00
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$	280.00	\$ 280.00
3	To renew rear windscreen to facilitate rear lid	S/N \$	480.00	\$ 480.00
4	To install solar film for rear windscreen.	S/N \$	400.00	
5	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$	480.00	\$ 480.00
6	To dismantle and renew rear bumper and rear lid. To cut out and reweld rear end panelling outer and inner. Re-organise rear crash management components. Reinstall all parts	\$	4,800.00	\$ 2,500.00
7	To respray rear bumper, rear lid, hinges, lhs rear fender and end panelling. To carry out joint sealer works and stone chip treatment.	\$	4,500.00	\$ 2,200.00
8	To renew lhs rear exhaust silencer. To align to	S/N \$	480.00	
9	To carry out water seepage test on rear	S/N \$	200.00	\$ 200.00
10	Supplementary	\$	3,200.00	\$ 2,650.00
11	Supplementary	\$	280.00	\$ 280.00
12	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 15,572.00	\$ 9,542.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 5405 B

S/N	Parts Description		<u>Damage Parts & Prices</u>	
			S/Nett	Remarks
1	REAR BUMPER		\$ 2,569.00	\$ 2,055.20
2	REAR BUMPER FIXING PARTS		\$ 225.00	
3	REAR BUMPER CARRIER		\$ 636.00	\$ 508.40
4	REAR BUMPER BRACKET HOLDER - LH / RH	2	\$ 440.00	\$ 352.00
5	REAR BUMPER SPOILER		\$ 273.00	\$ 218.00
6	REAR BUMPER GUIDE SECTION - LH / RH UPPER	2	\$ 38.00	
7	REAR PARKING AID SENSOR - INNER / OUTER	3	TBC	\$ 200.00
8	REAR BUMPER WIRING SET		\$ 510.00	
9	REAR LID		\$ 2,608.00	\$ 2,086.40
10	REAR LID ATTACHMENT PARTS		\$ 113.00	
11	REAR LID HINGE - LH / RH	2	\$ 452.00	\$ 361.60
12	REAR LID FLAP GASKET		\$ 222.00	\$ 177.60
13	REAR LID FLAP GASKET - UPPER REAR		\$ 100.00	
14	REAR LID STRIKER PLATE		\$ 122.00	
15	REAR LID LOCK		\$ 169.00	\$ 135.20
16	LID LOCK PUSH BUTTON		\$ 172.00	\$ 137.60
17	PACKING ADHESIVE		\$ 18.00	\$ 14.40
18	GAS FILLED STRUT	2	\$ 235.00	
19	AUDI EMBLEM		\$ 122.00	\$ 97.60
20	A5 INSCRIPTION		\$ 95.00	\$ 75.36
SUB TOTAL SPARE PARTS CHARGES			\$ 9,119.00	\$ 6,419.36

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 5405 B

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
		<i>c/f</i>		\$ 6,419.36
21	TFSI INSCRIPTION		\$ 95.00	\$ 75.36
22	REAR WINDSCREEN		\$ 1,108.00	\$ 886.40
23	PRIMER		\$ 19.00	\$ 14.96
24	LED TAIL LIGHT - LH / RH	2	\$ 2,450.00	\$ 980.00
25	LED TAIL LIGHT - LH / RH	2	\$ 1,716.00	\$ 686.00
26	LED LICENSE PLATE LIGHT	2	\$ 113.00	\$ 45.12
27	ADDITIONAL BRAKE LIGHT		\$ 446.00	\$ 356.40
28	REAR CROSS PANEL - OUTER		\$ 519.00	\$ 415.20
29	CROSS PANEL - LOWER		\$ 859.00	\$ 687.20
30	CROSS PANEL REINFORCEMENT - INNER		\$ 668.00	\$ 534.40
31	REAR CROSS PANEL TRIM		\$ 175.00	\$ 140.00
32	LUGGAGE COMPARTMENT FLOOR		\$ 701.00	
33	REAR LID TRIM PANEL		\$ 478.00	\$ 382.00
34	REAR SILENCER - LH		\$ 824.00	
35	REAR SILENCER DUAL CLIP		\$ 57.00	
36	REAR SILENCER BRACKET		\$ 57.00	
37	REAR NO PLATE	S/N	\$ 60.00	\$ 60.00
38	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
39	STONE CHIP	S/N	\$ 180.00	\$ 180.00
40	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
41	ACRYLIC SEALANT	S/N	\$ 180.00	\$ 180.00
42	SUPPLEMENTARY		\$ 114.00	\$ 90.24
43	SUNDRIES		\$ 400.00	\$ 86.08
TOTAL SPARE PARTS CHARGES		:	\$ 20,678.00	\$ 12,558.72
TOTAL LABOUR CHARGES		:	\$ 15,572.00	\$ 9,542.00
GRAND TOTAL		:	\$ 36,250.00	\$ 22,100.72

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0557/2020/NS 20-Aug-20 Glory Tan 1 OF 1 SKX 5405 B Audi A5 SB 1.8 TFSI MU 8T
Quantity	Description	Unit Price	Amount
Parts			
1	Rear lid guard plate	\$ 61.00	\$ 48.72
2	Rear lid cover for lock	\$ 8.00	\$ 6.00
3	Cable holder for rear lid trim panel	\$ 45.00	\$ 35.52
Labours			
1	To repair rhs tail lamp panel and lhs tail lamp panel.	\$ 1,200.00	\$ 1,000.00
2	To respray rhs tail lamp panel, lhs tail lamp panel and rhs rear fender	\$ 2,000.00	\$ 1,650.00
TOTAL		\$ 3,314.00	\$2,740.24

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0557/2020/NS 25-Aug-20 Glory Tan 1 OF 1 SKX 5405 B Audi A5 SB 1.8 TFSI MU 8T
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To dislodge and reinstall roof liner to facilitate the renewal of rear lid hinges.	s/n \$ 280.00	\$ 280.00
TOTAL		\$ 280.00	

For Premium Automobiles Pte Ltd

Authorised Signature