

Not Authored
1/1/2018

Trans-cab Auto Services Pte Ltd

AAD2008-037

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 62E

Vehicle No.: **18 AUG 2020**

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 62E

WDD2120012B222270

MERCEDES BENZ

E220 CDI

4.8.2020

DIRECT ASIA

16/12/2015

PART		LIST	
1	Front Fender LH	\$	<i>R</i> 1,067.78 <i>X</i>
1	Front Fender Inner Cowling LH	\$	<i>R</i> 211.23 <i>X</i>
1	Front Bumper	\$	<i>CM</i> 1,417.44 <i>✓</i>
1	Front Bumper Reinforcement	\$	569.72 <i>?</i>
1	Front Bumper Lower Grille Carrier	\$	<i>R</i> 125.10 <i>X</i>
1	Front Bumper Centre Mounting Frame	\$	98.04 <i>?</i>
1	Front Bumper Mounting Frame Bracket LH	\$	<i>R</i> 85.35 <i>X</i>
1	Front Bumper Inner Sponge Absorber	\$	147.37 <i>?</i>
1	Front Bumper Centre Air Grille	\$	<i>R</i> 78.12 <i>X</i>
1	Front Bumper Fog Lamp Grille LH	\$	<i>Dir</i> 50.70 <i>✓</i>
1	Front Bumper Fog Lamp Grille Cover Area LH	\$	<i>R</i> 33.48 <i>X</i>
1	Front Bumper Grille Cover Moulding LH	\$	<i>R</i> 105.66 <i>X</i>
1	Front Bumper Side Support Bracket	\$	<i>R</i> 57.83 <i>X</i>
1	Front Bumper Reinforcement Bracket	\$	<i>R</i> 305.34 <i>X</i>
1	Front Bumper Center Grille Lower Moulding Lip	\$	<i>R</i> 113.19 <i>X</i>
1	Front Bumper Lower Center Trim	\$	<i>R</i> 138.76 <i>X</i>
1	Front Bumper PDC Wiring Harness	\$	<i>R</i> 1,373.10 <i>X</i>
1	Front Rail Extension Support	\$	<i>R</i> 137.31 <i>X</i>
1	Front Headlamp LH	\$	<i>CM</i> 3,501.15 <i>✓</i>
1	Front Headlamp Panel LH	\$	<i>R</i> 275.80 <i>X</i>
1	Front Headlamp Bracket LH	\$	<i>CM</i> 150.67 <i>✓</i>
1	Headlamp Control Unit	\$	1,013.59 <i>?</i>
1	Engine lower splashshield front	\$	<i>R</i> 251.69 <i>X</i>
1	Lower Splashshield Mount Bracket LH	\$	<i>R</i> 43.11 <i>X</i>
1	Front Bonnet	\$	<i>R</i> 2,473.44 <i>✓</i>

Trans-cab Auto Services Pte Ltd**AAD2008-037**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 62E

1	Bonnet Star Logo	\$	<i>Sm</i>	100.30	X
1	Bonnet Lock Switch Bottom LH	\$	<i>Sm</i>	42.36	X
1	Bonnet Lock	\$	<i>R</i>	68.61	X
1	Bonnet Lock Latch Top LH	\$	<i>Di</i>	34.34	✓
1	Bonnet Opening Lever Handle Hook	\$	<i>Sm</i>	79.09	X
1	Front Bonnet Spring LH	\$	<i>Sm</i>	33.17	X
1	Bonnet Insulator	\$	<i>Sm</i>	277.75	X
1	Bonnet Damper Stay LH	\$	<i>Sm</i>	117.84	X
1	Bonnet Hinge LH	\$	<i>R</i>	157.03	X
1	Bonnet Weatherstrip	\$	<i>Sm</i>	26.86	X
1	Radiator Grille Support Beam	\$	<i>R</i>	263.99	X
1	Radiator Grille	\$	<i>CM</i>	814.17	✓
1	Upper Radiator Support Panel	\$	<i>R</i>	162.28	X
1	Air Duct Radiator Hood Top	\$	<i>Sm</i>	43.06	X
1	Radiator Fan Shroud Top Cover	\$	<i>Sm</i>	270.38	X
1	Air Duct Cooling Fan Bottom	\$	<i>Sm</i>	90.28	X
1	Windscreen Washer Tank	\$	<i>Sm</i>	121.22	X
1	Windscreen Washer Motor	\$	<i>Sm</i>	134.22	X
1	Front Windscreen	\$	<i>CM</i>	1,394.40	✓
1	Rain and Light Sensor Control Unit	\$		1,757.40	7
1	Rain and Light Sensor Cover	\$	<i>Sm</i>	175.74	X
1	Humidity and Temperature Sensor	\$	<i>na</i>	160.77	X
1	Dashboard	\$	<i>Tm</i>	3,816.00	✓
1	Steering Wheel	\$	<i>Sm</i>	1,900.00	X
1	Steering Column Switch Module Control Unit	\$	<i>na</i>	1,653.00	✓
1	Passenger Side Air Bag	\$	<i>na</i>	1,625.91	✓
1	Knee Air Bag	\$	<i>Sm</i>	956.81	X
1	Steering Wheel Air Bag	\$	<i>na</i>	2,658.00	✓
1	Front LH Seat Belt	\$	<i>Sm</i>	8,343.75	X
1	Front RH Seat Belt	\$	<i>Sm</i>	8,343.75	X
1	Front LH Seat Belt Lock	\$	<i>Sm</i>	140.29	X
1	Front RH Seat Belt Lock	\$	<i>Sm</i>	140.29	X
1	Airbag Computer	\$	<i>na</i>	1,119.34	✓
1	Rear Seat Belt LH	\$	<i>Tm</i>	502.50	✓

Trans-cab Auto Services Pte Ltd

AAD2008-037

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 62E

1	Rear Seat Belt RH	\$	7h	502.50	✓
1	Rear Seat Belt Center	\$	Sn	502.50	X
1	Rear Seat Belt LH Buckle	\$	Sn	96.73	X
1	Rear Seat Belt RH & Center Buckle (Twin Lock)	\$	Sn	231.37	X
1	Front LH Airbag Sensor	\$	nn	115.85	✓
1	Front RH Airbag Sensor	\$	nn	115.85	✓
1	Front Center Airbag Sensor	\$	nn	113.79	X

TOTAL \$ 53,028.46**10% \$ 5,302.85****\$ 47,725.61****Special Nett**

1 Set	Front Bumper Inner Frame Clip LH	\$	nn	90.00	✓
1 Set	Front Bumper Inner Frame Metal Clip LH	\$	nn	60.00	X
1 Set	Front Bumper clip	\$	nn	100.00	✓
1	Front Tyre LH	\$	Sn	550.00	X
1	Front Alloy Rim LH	\$	Sn	1,050.00	X
1 Set	Radiator Grille clip	\$	nn	75.00	✓
1 Set	Front Fender Protective Clip LH	\$	nn	65.00	X
1 Set	Front Fender Inner Cowling Insert Clip LH	\$	nn	75.00	X
1	Windscreen Moulding	\$	nn	300.00	✓
2	Windscreen Sealant	\$	nn	200.00	405N
1	Windscreen Inner Sponge Seal	\$	nn	170.00	X
1	Vehicle Plate Number with Garnish	\$	Sn	420.00	X
1	Front Bumper Fog Lamp Grille Clip	\$	nn	65.00	X
1	Front Bumper Center Air Grille Clip	\$	nn	70.00	X
1	Front Bumper Retainer Clip	\$	nn	80.00	X
1	Front Bumper Rivet	\$	nn	90.00	X
1	Dashboard Screw	\$	nn	65.00	X
1	Bonnet Insulator Clip	\$	nn	60.00	X

TOTAL \$ 3,585.00**TOTAL PARTS \$ 51,310.61**

Trans-cab Auto Services Pte Ltd**AAD2008-037**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 62E**LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	301
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of front bonnet fittings, attachment and perform water seepage test.	\$	n 170.00	X
Putty And Spray Painting Of The Affected Portion.	\$	3,500.00	8801
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	280.00	601
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, to Enable Repair.	\$	4 380.00	X
To Transfer Of Fender Fittings, Attachment And Perform Water Seepage Test.	\$	4 170.00	X
To Check Steering Geometry And Computer Wheel Alignment.	\$	4 220.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	1201
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To remove and refit air bag system and reset vehicle warning indicators.	\$	480.00	2501

To Transfer Of Tire, Rim And On Wheel Balancing. \$ 170.00
Trans-cab Auto Services Pte Ltd **AAD2008-037**
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHD 62E

Towing Fees \$ 180.00 *501*

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same \$ 3,500.00 *600*

TOTAL \$ 9,940.00

Over All Total \$ 61,250.61

REPAIR DAYS (Lump Sum) *25 DAYS*

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before ~~after~~ spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: