

Not Authored  
U/Sing &

**Trans-cab Auto Services Pte Ltd**

**AAD2008-037**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 62E**

Vehicle No.: 18 AUG 2020

**SHD 62E**

Chassis No.:

WDD2120012B222270

Vehicle Make:

MERCEDES BENZ

Vehicle Model:

E220 CDI

Date of Accident :

4.8.2020

Third Party Insurer :

**DIRECT ASIA**

Date of Registration:

16/12/2015

	<b>PART</b>		<b>LIST</b>
1	Front Fender LH	\$	R 1,067.78 X
1	Front Fender Inner Cowling LH	\$	Sm 211.23 X
1	Front Bumper	\$	CM 1,417.44 ✓
1	Front Bumper Reinforcement	\$	R 569.72 ? X
1	Front Bumper Lower Grille Carrier	\$	Sm 125.10 X
1	Front Bumper Centre Mounting Frame	\$	SVC 98.04 ? X
1	Front Bumper Mounting Frame Bracket LH	\$	R 85.35 X
1	Front Bumper Inner Sponge Absorber	\$	SVC 147.37 ? X
1	Front Bumper Centre Air Grille	\$	Sm 78.12 X
1	Front Bumper Fog Lamp Grille LH	\$	Dir 50.70 ✓
1	Front Bumper Fog Lamp Grille Cover Area LH	\$	Sm 33.48 X
1	Front Bumper Grille Cover Moulding LH	\$	Sm 105.66 X
1	Front Bumper Side Support Bracket	\$	R 57.83 X
1	Front Bumper Reinforcement Bracket	\$	R 305.34 X
1	Front Bumper Center Grille Lower Moulding Lip	\$	Sm 113.19 X
1	Front Bumper Lower Center Trim	\$	Sm 138.76 X
1	Front Bumper PDC Wiring Harness	\$	Sm 1,373.10 X
1	Front Rail Extension Support	\$	R 137.31 X
1	Front Headlamp LH	\$	CM 3,501.15 ✓
1	Front Headlamp Panel LH	\$	R 275.80 X
1	Front Headlamp Bracket LH	\$	CM 150.67 ✓
1	Headlamp Control Unit	\$	SVC 1,013.59 ? X
1	Engine lower splashshield front	\$	Sm 251.69 X
1	Lower Splashshield Mount Bracket LH	\$	Sm 43.11 X
1	Front Bonnet	\$	R 2,473.44 ✓

**Trans-cab Auto Services Pte Ltd**

AAD2008-037

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 62E**

1	Bonnet Star Logo	\$	Per	100.30	X
1	Bonnet Lock Switch Bottom LH	\$	Per	42.36	X
1	Bonnet Lock	\$	R	68.61	X
1	Bonnet Lock Latch Top LH	\$	DIY	34.34	✓
1	Bonnet Opening Lever Handle Hook	\$	Per	79.09	X
1	Front Bonnet Spring LH	\$	Per	33.17	X
1	Bonnet Insulator	\$	Per	277.75	X
1	Bonnet Damper Stay LH	\$	Per	117.84	X
1	Bonnet Hinge LH	\$	X	157.03	X
1	Bonnet Weatherstrip	\$	Per	26.86	X
1	Radiator Grille Support Beam	\$	R	263.99	X
1	Radiator Grille	\$	CM	814.17	✓
1	Upper Radiator Support Panel	\$	R	162.28	X
1	Air Duct Radiator Hood Top	\$	Per	43.06	X
1	Radiator Fan Shroud Top Cover	\$	Per	270.38	X
1	Air Duct Cooling Fan Bottom	\$	Per	90.28	X
1	Windscreen Washer Tank	\$	Per	121.22	X
1	Windscreen Washer Motor	\$	Per	134.22	X
1	Front Windscreen	\$	CM	1,394.40	✓
1	Rain and Light Sensor Control Unit	\$	SVC	1,757.40	7X
1	Rain and Light Sensor Cover	\$	Per	175.74	X
1	Humidity and Temperature Sensor	\$	NA	160.77	X
1	Dashboard	\$	TA	3,816.00	✓
1	Steering Wheel	\$	Per	1,900.00	X
1	Steering Column Switch Module Control Unit	\$	NA	1,653.00	✓
1	Passenger Side Air Bag	\$	Per	1,625.91	✓
1	Knee Air Bag	\$	Per	956.81	X
1	Steering Wheel Air Bag	\$	Per	2,658.00	✓
1	Front LH Seat Belt	\$	Per	8,343.75	X
1	Front RH Seat Belt	\$	Per	8,343.75	X
1	Front LH Seat Belt Lock	\$	Per	140.29	X
1	Front RH Seat Belt Lock	\$	Per	140.29	X
1	Airbag Computer	\$	ME	1,119.34	✓
1	Rear Seat Belt LH	\$	TA	502.50	✓

**Trans-cab Auto Services Pte Ltd**

AAD2008-037

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 62E**

1	Rear Seat Belt RH	\$	<i>Jn</i>	502.50	✓
1	Rear Seat Belt Center	\$	<i>Sn</i>	502.50	X
1	Rear Seat Belt LH Buckle	\$	<i>Sn</i>	96.73	X
1	Rear Seat Belt RH & Center Buckle (Twin Lock)	\$	<i>Sn</i>	231.37	X
1	Front LH Airbag Sensor	\$	<i>Nn</i>	115.85	✓
1	Front RH Airbag Sensor	\$	<i>Nn</i>	115.85	✓
1	Front Center Airbag Sensor	\$	<i>Nn</i>	113.79	X

**TOTAL \$ 53,028.46****10% \$ 5,302.85****\$ 47,725.61****Special Nett**

1 Set	Front Bumper Inner Frame Clip LH	\$	<i>Nn</i>	90.00	✓
1 Set	Front Bumper Inner Frame Metal Clip LH	\$	<i>Nn</i>	60.00	X
1 Set	Front Bumper clip	\$	<i>Nn</i>	100.00	✓
1	Front Tyre LH	\$	<i>Sn</i>	550.00	X
1	Front Alloy Rim LH	\$	<i>Sn</i>	1,050.00	X
1 Set	Radiator Grille clip	\$	<i>Nn</i>	75.00	✓
1 Set	Front Fender Protective Clip LH	\$	<i>Nn</i>	65.00	X
1 Set	Front Fender Inner Cowling Insert Clip LH	\$	<i>Nn</i>	75.00	X
1	Windscreen Moulding	\$	<i>Nn</i>	300.00	✓
2	Windscreen Sealant	\$	<i>Nn</i>	200.00	<i>40SN</i>
1	Windscreen Inner Sponge Seal	\$	<i>Nn</i>	170.00	X
1	Vehicle Plate Number with Garnish	\$	<i>Sn</i>	420.00	X
1	Front Bumper Fog Lamp Grille Clip	\$	<i>Nn</i>	65.00	X
1	Front Bumper Center Air Grille Clip	\$	<i>Nn</i>	70.00	X
1	Front Bumper Retainer Clip	\$	<i>Nn</i>	80.00	X
1	Front Bumper Rivet	\$	<i>Nn</i>	90.00	X
1	Dashboard Screw	\$	<i>Nn</i>	65.00	X
1	Bonnet Insulator Clip	\$	<i>Nn</i>	60.00	X

**TOTAL \$ 3,585.00****TOTAL PARTS \$ 51,310.61**

**Trans-cab Auto Services Pte Ltd**

AAD2008-037

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 62E

**LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	301
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of front bonnet fittings, attachment and perform water seepage test.	\$	n 170.00	X
Putty And Spray Painting Of The Affected Portion.	\$	3,500.00	8801
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	280.00	601
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, to Enable Repair.	\$	4 380.00	X
To Transfer Of Fender Fittings, Attachment And Perform Water Seepage Test.	\$	4 170.00	X
To Check Steering Geometry And Computer Wheel Alignment.	\$	4 220.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	1201
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To remove and refit air bag system and reset vehicle warning indicators.	\$	480.00	2501

To Transfer Of Tire, Rim And On Wheel Balancing. \$

170.00

**Trans-cab Auto Services Pte Ltd**

**AAD2008-037**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 62E**

Towing Fees

\$

180.00

*501*

Panel Beating, Knocking And Straightening The  
Necessary Portion, Remove And Renewal Of Parts,  
Adjust And Realign The Same

\$

3,500.00

*600*

**TOTAL**

\$

**9,940.00**

**Over All Total**

\$

**61,250.61**

**REPAIR DAYS (Lump Sum)**

*25* DAYS

*7 days*

**For Official Use**

Prepared By : \_\_\_\_\_  
(Accident Dept)

Verify By : \_\_\_\_\_  
(Accident Workshop)

Checked By : \_\_\_\_\_  
(Finance Dept)

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before ~~after~~ spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: