

Bifrost Auto Pte Ltd

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875
Tel: 65 64524457 / Fax: +65 64524584

CO. Reg. No.: 201929175W

Model : **BMW 316I 1.6 AT**
Registraion No : **SKJ 5713 K**
Chassis No: **WBA3A12090J720126**
Year of Manufacturing: **2013**

S/No	Qty	Items	Unit Price	Amount
1	1	Front Bumper	\$ 1,987.40	\$ 1,987.40
2	1	Front Bumper Retainer (LHS) X	\$ 89.70	\$ 89.70
3	1	Front Bumper Retainer (RHS) X	\$ 89.70	\$ 89.70
4	1	Front Bumper Bracket (LHS) X	\$ 94.60	\$ 94.60
5	1	Front Bumper Bracket (RHS) X	\$ 94.60	\$ 94.60
6	1	Front Bumper Reinforcement X	\$ 874.60	\$ 874.60
7	1	Front Bumper Sponge X	\$ 265.40	\$ 265.40
8	1	Front Bumper Fog Light X	\$ 412.50	\$ 412.50
9	1	Front Bumper Fog Light Cover X	\$ 167.80	\$ 167.80
10	1	Front Bumper Lower Grille X	\$ 369.70	\$ 369.70
11	1	Front Bumper Radiator Grille (LHS) X	\$ 256.40	\$ 256.40
12	1	Front Bumper Radiator Grille (RHS) X	\$ 256.40	\$ 256.40
13	1	Front Bumper Lower Lip X	\$ 789.40	\$ 789.40
14	1	Headlamp (LHS) X	\$ 1,880.40	\$ 1,880.40
15	1	Headlamp Nozzle (LHS) X	\$ 154.10	\$ 154.10
16	1	Front Fender (LHS) X	\$ 1,154.60	\$ 1,154.60
17	1	Front Fender Shield (LHS) X	\$ 315.40	\$ 315.40
18	1	LHS Front Absorber X	\$ -	\$ -
19	1	LHS Front Lower Arm X	\$ -	\$ -
20	1	LHS Front Upper Arm X	\$ -	\$ -
21	1	LHS Front Knuckle X	\$ -	\$ -
22	1	LHS Front Knuckle Hub X	\$ -	\$ -
23	1	LHS Front Wheel Bearing X	\$ -	\$ -

\$ 9,252.70

-5% \$ 4.63

Total for spare parts \$ 9,248.07

Special Nett	p	Items	Unit Price	Amount
1	10	Front Bumper Clip	\$ 9.00	\$ 90.00
2	10	LHS Front Fender Shield Clip	\$ 9.00	\$ 90.00
3	1	LHS Front Rim Repair X	\$ 2,500.00	\$ 2,500.00
4	1	LHS Front Tyre X	\$ 900.00	\$ 900.00

Total for SP \$ 3,580.00

Sub-Total for Parts : \$ 12,828.07

NO	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	1,200.00 400
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	1,000.00 500
3		Apply rust proofing on the adjacent panels	\$	50.00
4		To supply under coating / putty on parts replaced	\$	50.00 } 40.
5		To perform water seepage test after repair	\$	80.00 XNN
6		To conduct headlamp focus	\$	100.00
7		To check wiring and lighting system	\$	50.00 } 50.
8		Check and re-adjust wheel alignment	\$	150.00 ?
9		Reset engine management system with diagnostic fault	\$	120.00 XNN

TOTAL AMOUNT : \$ 2,800.00
OVERALL COST: \$ 15,628.07

4 Days .
Lumpsum repair .
After repair photos .
Gmo Qianp
19/8/2020 .

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: