

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
SIN MING AUTOCITY, SINGAPORE 575722.
Tel No. : 64536256/64563715 Fax No. : 64557754
E-Mail : kumchew1@singnet.com.sg
GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

MSIG INSURANCE (SINGAPORE) PTE LTD
16, RAFFLES QUAY #24-01
HONG LEONG BUILDING, SINGAPORE 048581
motorsurvey@sg.msig-asia.com

Attention : Motor Claim Department
Contact : 68277888 Fax No. : 66431349

*Not Authorise
L1 Imp & 3250p
Resurvey After Paint
5days*

Estimate : ES005018

Date : 25/08/2020
Vehicle Num. : GBH 2262 G
Make/Model : TOYOTA HIACE-2016
Chassis/Eng# : KDH2015025364/1KD2678003
Accident Date : 17/08/2020
Claim No. :
Reference : KC/TP2262/2008-05
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|-----|-------|--------------------------|--|--|
| 1. | 1 PC | REAR BUMPER | | |
| 2. | 2 PCS | REAR BUMPER RETAINER | | |
| 3. | 1 PC | REAR BUMPER BRACKET | | |
| 4. | 1 PC | REAR LAMP - RH | | |
| 5. | 1 PC | REAR END PANEL | | |
| 6. | 1 PC | REAR END PANEL GARNISH | | |
| 7. | 1 PC | REAR LID <i>1950</i> | | |
| 8. | 1 PC | REAR LID LOCK | | |
| 9. | 1 PC | REAR LID LOCK GARNISH | | |
| 10. | 1 PC | REAR LID EMBLEM | | |
| 11. | 1 PC | REAR LID RUBBER | | |
| 12. | 1 PC | REAR LID 'HIACE' STICKER | | |

List Total S\$:
25.00% Discount S\$:

38.99	371.73	✓
	77.98	X
	42.55	X
	288.86	✓
	336.28	✓
	161.35	X
	2,010.07	✓
	262.53	✓
	45.72	✓
	52.45	✓
	365.74	X
	48.93	✓
	4,064.19	
	1,016.05	
	3,048.14	

- | | | | | |
|----|-------|----------------------------|--|--|
| 1. | 1 PC | REAR LID 'AIRSIDE' STICKER | | |
| 2. | 1 SET | REVERSE SENSOR | | |

Special Nett Total S\$:

25.00	✓
280.00	✓
305.00	

LABOUR :

TO PULL, KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART.

450.00 ✓

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

KUM CHEW MOTOR WORKSHOP

60, SIN MING DRIVE #05-08
 SIN MING AUTOCITY, SINGAPORE 575722.
 Tel No. : 64536256/64563715 Fax No. : 64557754
 E-Mail : kumchew1@singnet.com.sg
 GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

MSIG INSURANCE (SINGAPORE) PTE LTD
 16, RAFFLES QUAY #24-01
 HONG LEONG BUILDING, SINGAPORE 048581
 motorsurvey@sg.msig-asia.com

Attention : Motor Claim Department
 Contact : 68277888 Fax No. : 66431349

Estimate : ES005018

Date : 25/08/2020
 Vehicle Num. : GBH 2262 G
 Make/Model : TOYOTA HIACE-2016
 Chassis/Eng# : KDH2015025364/1KD2678003
 Accident Date : 17/08/2020
 Claim No. :
 Reference : KC/TP2262/2008-05
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO SPRAY & PAINT ON ACCIDENT PORTION.		550/ 800.00
		TO DISMANTLE & REFIX REAR WINDSCREEN.	120/	180.00
		TO DISMANTLE & REPLACE 1 SET REVERSE SENSOR.	50/	80.00
		TO ANTI-RUST REAR AFFECTED AREAS.		60.00 ✓
		TO CHECK REAR ELECTRICAL WIRING SYSTEM.	20/	60.00
		TO REMOVE/TRANSFER REAR LID MOTOR DOOR GEAR & DOOR MECHANISMS.	60/	150.00
		Labour Total S\$:		1,780.00

ngDollars : Five Thousand One Hundred Thirty-Three & Cents Fourteen Only

Total S\$: 5,133.14
 =====

KUM CHEW MOTOR WORKSHOP