



12-Aug-2020

North Spring Biz Hub
No. 9 Yishun Industrial St 1
#01-67
Singapore 768163
Email : racing.stripes78@gmail.com

Attn.

Repair Quotation of FBD3773Z

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Quotation

4,780
- 10%
P = 4,302.0
L = 700

5,002
- 20%

4,001.60

US
\$4,000

4 days

DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1. Repleacment of Fork Tube / BT	2	\$290.00	\$580.00 //
2. Fork Seal / Nec	2	\$80.00	\$160.00 //
3. Head Fairing / CRU	1	\$600.00	\$600.00 //
4. Front Fender / CRU	1	\$180.00	\$180.00 //
5. Tank cover / CRA	1	\$700.00	\$700.00 //
6. Side Fairing / CRA	2	\$310.00	\$620.00 //
7. Bottom Fairing / CRA	1	\$450.00	\$450.00 400
8. Headlight / MTS	1	\$550.00	\$550.00 //
9. Head Lamp Holder / BT	1	\$240.00	\$240.00 //
10. Full Fairing spray and repair of Tail Fairing	1	\$650.00	\$650.00 300
11. Front rim straighten and respray	1	\$250.00	\$250.00 100
12. Replace Radiator / BT	1	\$650.00	\$650.00 //
13. Signal lights / CRU	2	\$50.00	\$100.00 //
14. Labour	1	\$650.00	\$650.00 300
Total			\$7,180.00

Yours faithfully

Prakash Naidu
Director
Racing Stripes Pte Ltd
Tel : 92974194