




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI20008673/T1tf3e2		
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 20-11-2020		
		Code : AGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMD 4340S	Veh. Inspected	SME 8707L	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10007055	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	19/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT HYBRID 1.5	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	GP53416047	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/08/2020	Inspection Date	19/08/2020	
Survey held at	160 SIN MING DRIVE #06-02			
Repairer	MBM WHEELPOWER PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		