

WHEELPOWER PTE LTD

Our Ref: SMD4340S

ur Ref: SME8707L

o: General Insurance (Singapore) Pte Ltd

CC

Fax

Date: 19/8/2020
 From: Eryx Tan
 Fax: 64525333
 Contact: 8138 7188
 Make / Model: HONDA FIT HYBRID 1.5A
 Chassis No.: GP53416047
 Engine No.: LEB6070789
 Year of Make: 2018
 Accident Date: 18 August 2020

ESTIMATE FOR VEHICLE NO. : SME8707L

DESCRIPTION	QTY	List Price
REAR WINDSCREEN MOULDING	1	\$ 125.00 <i>net</i>
TAILGATE	1	\$ 1,950.00 <i>880.40/b6</i>
TAILGATE WEATHERSTRIP	1	\$ 85.00 <i>twi</i>
TAILGATE OUTER MOULDING	1	\$ 480.00 <i>nn x</i>
TAILGATE INNER TRIM	1	\$ 550.00 <i>341.80 ana</i>
TAILGATE INNER TRIM CLIPS	10	\$ 90.00 <i>net</i>
TAILGATE HINGE LH	1	\$ 80.00 <i>ky</i>
TAILGATE HINGE RH	1	\$ 80.00 <i>Ry</i>
TAILGATE LOCK	1	\$ 155.00 <i>bt</i>
TAILGATE STRIKER	1	\$ 40.00 <i>nn x</i>
TAILGATE HONDA LOGO	1	\$ 22.00 <i>net</i>
TAILGATE "FIT" EMBLEM	1	\$ 38.00 <i>net</i>
TAILGATE "HYBRID" EMBLEM	1	\$ 65.00 <i>net</i>
TAIL LAMP LH	1	\$ 550.00 <i>366</i>
TAIL LAMP RH	1	\$ 550.00 <i>net</i>
TAILGATE LAMP LH	1	\$ 480.00 <i>nn x</i>
TAILGATE LAMP RH	1	\$ 480.00 <i>nn x</i>
REAR BUMPER	1	\$ 950.00 <i>566.50</i>
REAR BUMPER CLIPS	10	\$ 90.00 <i>30 net</i>
REAR BUMPER LOWER TRIM	1	\$ 150.00 <i>de</i>
REAR RH BUMPER SIDE RETAINER LH	1	\$ 35.00 <i>net</i>
REAR RH BUMPER SIDE RETAINER RH	1	\$ 35.00 <i>x</i>
REAR LH BUMPER SPONGE	2	\$ 180.00 <i>net</i>
REAR BUMPER REFLECTOR LH	1	\$ 90.00 <i>net</i>
REAR BUMPER REFLECTOR RH	1	\$ 90.00 <i>x</i>
END PANEL - photo	1	\$ 550.00 <i>390.60</i>
END PANEL TOP GARNISH	1	\$ 180.00 <i>de</i>
END PANEL TOP GARNISH CLIPS	10	\$ 90.00 <i>net</i>

SPARE WHEEL COMPARTMENT

HYBRID BATTERY

REAR FENDER LH

REAR FENDER INNER TRIM LH

REAR FENDER INNER TRIM RH

REAR FENDER INNER SHIELD LH

REAR MAIN CHASSIS LH

SPARE TYRE COMPARTMENT BOARD

1	\$	Rx	1,100.00
1	\$	5000 h/v	11,800.00
1	\$	Rx	850.00
1	\$	385 de	680.00
1	\$	nn x	680.00
1	\$	nn x	85.00
1	\$	Rx	580.00
1	\$	nn x	450.00

Total:	\$	24,485.00
LESS 20%	\$	(4,897.00)
Parts Total:	\$	19,588.00

SPECIAL NETT

WINDSCREEN SEALANT

BODY SEALANT

REAR NUMBER PLATE WITH FRAME

REAR BUMPER SENSORS

1	\$	net	50.00
1	\$	40	80.00
1	\$	nn x	60.00
1 SET	\$	nw 200	300.00

LABOUR

TO REMOVE, REFIT & REPAIR REAR DAMAGED PORTIONS.

TO CHECK & RECONNECT ALL NECESSARY WIRING

TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR

TO REMOVE & INSTALL REAR UPHOLSTERY TO FACILITATE REPAIR

TO DISMANTLE & TRANSFER TAILGATE FITTINGS & MECHANISM TO NEW TAILGATE / FACILITATE REPAIR

TO REMOVE & REPLACE BUMPER SENSORS

TO APPLY ANTI RUST COATING

TO CONDUCT CHASSIS ALIGNMENT ON CAR-O-LINER

TO SPRAY PAINT ON THE AFFECTED AREAS

\$	11.00	2,000.00
\$	800	
\$	30	120.00
\$	50.60	100.00
\$	50	120.00
\$	60	100.00
\$	30	60.00
\$	30	250.00
\$	photo 30	350.00
\$	1000 800	1,200.00

Tanpin 97495449 / 67418434
WP

Total:	\$	24,378.00
7% GST:	\$	1,706.46
Grand Total:	\$	26,084.46

19/8/20 @ 320 pm
Recovery after repair
bumpers - 6 days - 7 days
tanpin@lhaauto.com