

WHEELPOWER PTE LTD

Our Ref: SMD4340S

ur Ref: SME8707L


o: General Insurance (Singapore) Pte Ltd

CC

Fax

Date: 19/8/2020
 From: Eryx Tan
 Fax: 64525333
 Contact: 8138 7188
 Make / Model: HONDA FIT HYBRID 1.5A
 Chassis No.: GP53416047
 Engine No.: LEB6070789
 Year of Make: 2018
 Accident Date: 18 August 2020

ESTIMATE FOR VEHICLE NO. : SME8707L



DESCRIPTION	QTY	List Price
REAR WINDSCREEN MOULDING	1	\$ 125.00 <i>net</i>
TAILGATE	1	\$ 1,950.00 <i>880.40/b6</i>
TAILGATE WEATHERSTRIP	1	\$ 85.00 <i>twi</i>
TAILGATE OUTER MOULDING	1	\$ 480.00 <i>nn x</i>
TAILGATE INNER TRIM	1	\$ 550.00 <i>341.80 ana</i>
TAILGATE INNER TRIM CLIPS	10	\$ 90.00 <i>net</i>
TAILGATE HINGE LH	1	\$ 80.00 <i>ky</i>
TAILGATE HINGE RH	1	\$ 80.00 <i>Ry</i>
TAILGATE LOCK	1	\$ 155.00 <i>bt</i>
TAILGATE STRIKER	1	\$ 40.00 <i>nn x</i>
TAILGATE HONDA LOGO	1	\$ 22.00 <i>net</i>
TAILGATE "FIT" EMBLEM	1	\$ 38.00 <i>net</i>
TAILGATE "HYBRID" EMBLEM	1	\$ 65.00 <i>net</i>
TAIL LAMP LH	1	\$ 550.00 <i>366</i>
TAIL LAMP RH	1	\$ 550.00 <i>net</i>
TAILGATE LAMP LH	1	\$ 480.00 <i>nn x</i>
TAILGATE LAMP RH	1	\$ 480.00 <i>net</i>
REAR BUMPER	1	\$ 950.00 <i>566.50</i>
REAR BUMPER CLIPS	10	\$ 90.00 <i>30 net</i>
REAR BUMPER LOWER TRIM	1	\$ 150.00 <i>de</i>
REAR RH BUMPER SIDE RETAINER LH	1	\$ 35.00 <i>net</i>
REAR RH BUMPER SIDE RETAINER RH	1	\$ 35.00 <i>net</i>
REAR LH BUMPER SPONGE	2	\$ 180.00 <i>net</i>
REAR BUMPER REFLECTOR LH	1	\$ 90.00 <i>net</i>
REAR BUMPER REFLECTOR RH	1	\$ 90.00 <i>net</i>
END PANEL - photo	1	\$ 550.00 <i>390.60</i>
END PANEL TOP GARNISH	1	\$ 180.00 <i>de</i>
END PANEL TOP GARNISH CLIPS	10	\$ 90.00 <i>net</i>

SPARE WHEEL COMPARTMENT	1	\$	Rx 1,100.00
HYBRID BATTERY	1	\$	ht ✓ 11,800.00
REAR FENDER LH	1	\$	Rx 850.00
REAR FENDER INNER TRIM LH	1	\$	385 de ✓ 680.00
REAR FENDER INNER TRIM RH	1	\$	nn x 680.00
REAR FENDER INNER SHIELD LH	1	\$	nn x 85.00
REAR MAIN CHASSIS LH	1	\$	Rx 580.00
SPARE TYRE COMPARTMENT BOARD	1	\$	nn. x 450.00

Total:	\$	24,485.00
LESS 20%	\$	(4,897.00)
Parts Total:	\$	19,588.00

SPECIAL NETT

WINDSCREEN SEALANT	1	\$	net 50.00
BODY SEALANT	1	\$	40 80.00
REAR NUMBER PLATE WITH FRAME	1	\$	nn. x 60.00
REAR BUMPER SENSORS	1 SET	\$	nw ✓ 200 300.00

LABOUR

TO REMOVE, REFIT & REPAIR REAR DAMAGED PORTIONS.	\$	11.00 2,000.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	800. 120.00
TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR	\$	30. 100.00
TO REMOVE & INSTALL REAR UPHOLSTERY TO FACILITATE REPAIR	\$	50. 120.00
TO DISMANTLE & TRANSFER TAILGATE FITTINGS & MECHANISM TO NEW TAILGATE / FACILITATE REPAIR	\$	50. 120.00
TO REMOVE & REPLACE BUMPER SENSORS	\$	60. 100.00
TO APPLY ANTI RUST COATING	\$	30. 60.00
TO CONDUCT CHASSIS ALIGNMENT ON CAR-O-LINER	\$	30. 250.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	photo 30. 350.00 250
	\$	1000 800 1,200.00

Total:	\$	24,378.00
7% GST:	\$	1,706.46
Grand Total:	\$	26,084.46

Tanpin 97495449 / 67418434
WP

19/8/20 @ 320 pm
Recovery after repair
insurance - 6 days - 7 days
tanpin@lhaauto.com