

MBM WHEELPOWER PTE LTD

Your Ref: SMD4340S

Our Ref: SME8707L

To: General Insurance (Singapore) Pte Ltd

CC

Fax

Date: 28/8/2020
From: Eryx Tan
Fax: 64525333
Contact: 8138 7188
Make / Model: HONDA FIT HYBRID 1.5A
Chassis No.: GP53416047
Engine No.: LEB6070789
Year of Make: 2018
Accident Date: 18 August 2020

SUPPLEMENTARY FOR VEHICLE NO. : SME8707L

DESCRIPTION

TAILLAMP INNER PANEL LH
BUZZER SENSOR
ANTENNA SENSOR
REAR FLOOR PANEL LH

QTY

List Price

1	\$	bt✓	220.00
1	\$	wa✓	95.00
1	\$	wa✓	95.00
1	\$	bt✓	280.00

Total: \$ 690.00

LESS 20% \$ (138.00)

Parts Total: \$ 552.00

SPECIAL NETT

REVERSE CAMERA

1	\$	200 rw✓	250.00
---	----	---------	--------

LABOUR

TO DIAGNOSE VEHICLE CANNOT START BEFORE REPAIR
TO REMOVE & REPLACE REAR WINDSCREEN
TO REMOVE & REPLACE REVERSE CAMERA

\$	✓	150.00
----	---	--------

\$	✓	120.00
----	---	--------

\$	30	80.00
----	----	-------

Total: \$ 1,152.00

7% GST: \$ 80.64

Grand Total: \$ 1,232.64

mbm wheelpower

Mbm wheelpower pte ltd

160 SIN MING DRIVE #06-02

SIN MING AUTOCITY

t 62628888 f 64525333

Company Registration Number : 200204110W