


# MBM WHEELPOWER PTE LTD



Your Ref: SMD4340S  
Our Ref: SME8707L

To: General Insurance ( Singapore ) Pte Ltd

CC

Fax

Date: 28/8/2020  
From: Eryx Tan  
Fax: 64525333  
Contact: 8138 7188  
Make / Model: HONDA FIT HYBRID 1.5A  
Chassis No.: GP53416047  
Engine No.: LEB6070789  
Year of Make: 2018  
Accident Date: 18 August 2020

SUPPLEMENTARY FOR VEHICLE NO. : SME8707L

## DESCRIPTION

DESCRIPTION	QTY		List Price
TAILLAMP INNER PANEL LH	1	\$	bt✓ 220.00
BUZZER SENSOR	1	\$	wa✓ 95.00
ANTENNA SENSOR	1	\$	wa✓ 95.00
REAR FLOOR PANEL LH	1	\$	bt✓ 280.00
Total:		\$	690.00
LESS 20%		\$	(138.00)
<b>Parts Total:</b>		<b>\$</b>	<b>552.00</b>

## SPECIAL NETT

REVERSE CAMERA	1	\$	200 rw✓ 250.00
----------------	---	----	----------------

## LABOUR

TO DIAGNOSE VEHICLE CANNOT START BEFORE REPAIR		\$	✓ 150.00
TO REMOVE & REPLACE REAR WINDSCREEN		\$	✓ 120.00
TO REMOVE & REPLACE REVERSE CAMERA		\$	30 80.00

Total:	\$	1,152.00
7% GST:	\$	80.64
<b>Grand Total:</b>	<b>\$</b>	<b>1,232.64</b>