

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06212

Vehicle Insured : GBJ2866D

Accident Date : 14-Aug-2020

Date : 17-Aug-2020

Our Ref : 020092 (GREAT AMER) / CHAN

PAGE : 1

ENGENUITZ

180D RIVERVALE CRESCENT

#18-393

Singapore 544180

Not Authorized
C/Rep 850006
Passing After Point 5 days

ESTIMATED COST OF REPAIR FOR HONDA VEZEL 1.5Z HYBRIDCVT ABS SLE4488G

1 pc	Tail gate				\$1,150.00	
1 pc	Tail gate	glass moulding			Rx	
2 pcs	Tail gate lamp	oil set nls caps	@ \$8389.30			
1 pc	Tail gate outer garnish	wage				
1 pc	Tail gate "VEZEL" emblem	nrs			778.60	
1 pc	Tail gate "HYBRID" emblem	nrs			220.00	
1 pc	Tail gate inner lock	nrs			43.00	
1 pc	Tail gate rubber	Cut			75.50	
1 pc	Tail gate inner trim cover	Cut			157.10	
1 pc	N/s taillamp	nrs			118.30	508in
1 pc	Rear bumper fascia	Cut			183.40	
2 pcs	Rear bumper side bumper	Bkr			474.80	
1 pc	Rear end panel	nrs			798.10	
2 pcs	Rear bumper side retainer	Ry	@ \$8195.00		390.00	x
					Ry 411.90	
			@ \$817.50		Rn 35.00	X

Less 20% :	4,970.70
	994.14

1 pc	Rear w/s glass sealant
1 pc	Rear bumper reverse sensor
1 pc	Rear reverse camera
1 pc	Rear no.plate with box

To remove & refix rear windscreen glass and conduct water leak test.

	3,976.56	4000
Net	60.00	sn
Short	200.00	sn
sn	300.00	sn
del	450.00	sn
	150.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBJ2866D

Page : 2

To remove roof lining, front and rear seats, trim board and carpet

bol
120.00

To apply undersealing

bol
100.00

To putty and spray replaced parts

bol
900.00

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

bol
900.00

Total : S\$ 6,856.56
=====

Singapore Dollars Six Thousand Eight Hundred and Fifty Six and Cents Fifty Six Only

7378.80

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBJ2866D (GREAT AMER)

Accident Date : 14-08-2020

Date : 02-09-2020

Our Ref : 020092 / CHAN

ENGENUIZ

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR HONDA VEZEL 1.5Z HYBRID CVT ABS SLE4488G

1 PC	END PANEL TOP GARNISH	Net	\$98.00	✓
1 PC	O/S TAILLAMP	Net	\$474.80	✓
1 PC	END PANEL BUZZER SENSOR	Net	\$80.00	✓
			\$652.80	
		LESS 20%	\$130.56	
			<u>\$522.24</u>	

Singapore Dollars Five Hundred Twenty Two And Cents Twenty Four Only