



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

Not Authorised

Estimate No: ES2000076
Date: 24 Aug 2020

Policy No:
Veh Reg No: CB6873L
Make/Model: NISSAN URVAN

Chassis No: JN1HG4E25Z0701424

Engine No: ZD30020985

Reg. Date: 30/11/2002

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party *LKK Auto Consultants* hence notify

Accident Date: 13/08/2020 the Repairer of the following:

TP Veh Reg No: SHC7284R

3 days
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
Estimate Repair Cost to Vehicle No : CB6873L

Description	U/Price	Quantity	List Price SS	Amount SS
Spare Parts				
1 FRONT BUMPER	Acknowledged by Repairer 572.80	1 PC	<i>By</i> 572.80	<i>✓</i>
2 FRONT BUMPER CLIPS	Signature: 50.00	1 SET	<i>nn</i> 50.00	<i>✓</i>
3 FRONT BUMPER FOG LAMP GARNISH - LH	Date: 85.00	1 PC	<i>nn</i> 85.00	<i>✓</i>
4 FRONT BUMPER SIDE RETAINER - LH	137.20	1 PC	<i>nn</i> 137.20	<i>✓</i>
5 FRONT BUMPER SIDE RETAINER - RH	137.20	1 PC	<i>nn</i> 137.20	<i>X</i>
6 FRONT CORNER FENDER - LH	223.90	1 PC	<i>nn</i> 223.90	<i>X</i>
7 FRONT DOOR OUTER MOULDING - LH	152.90	1 PC	<i>nn</i> 152.90	<i>X</i>
8 FRONT DOOR - LH	1,668.50	1 PC	<i>nn</i> 1,668.50	<i>X</i>
9 FRONT DOOR WEATHERSTRIP - LH	125.60	1 PC	<i>nn</i> 125.60	<i>X</i>
10 FRONT DOOR HINGE BOTTOM	82.50	1 PC	<i>nn</i> 82.50	<i>X</i>
11 FRONT DOOR HINGE TOP	82.50	1 PC	<i>nn</i> 82.50	<i>X</i>
12 FRONT DOOR INNER TRIM - LH	420.00	1 PC	<i>nn</i> 420.00	<i>X</i>
13 FRONT DOOR LOCK - LH	320.00	1 PC	<i>nn</i> 320.00	<i>X</i>
14 FRONT HEADLAMP - LH	858.40	1 PC	<i>nn</i> 858.40	<i>?</i>
15 FRONT TOP STEP GARNISH - LH	185.30	1 PC	<i>nn</i> 185.30	<i>X</i>
16 FRONT STEP GARNISH CLIP	30.00	1 SET	<i>nn</i> 30.00	<i>X</i>
17 FRONT BUMPER FOG LAMP - LH	380.50	1 PC	<i>nn</i> 380.50	<i>✓</i>
18 FRONT SIDE LAMP - LH	185.90	1 PC	<i>nn</i> 185.90	<i>?</i>
19 FRONT DOOR STICKER	30.00	1 PC	<i>nn</i> 30.00	<i>X</i>
20 FRONT BUMPER REINFORCEMENT	480.50	1 PC	<i>nn</i> 480.50	<i>?</i>
21 FRONT GRILLE	280.50	1 PC	<i>nn</i> 280.50	<i>X</i>
			6,489.20	6,489.20

Labour

22 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,200.00	1 JOB	1,200.00	<i>25d</i>
23 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,000.00	1 JOB	1,000.00	<i>32d</i>
24 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	80.00	1 JOB	<i>nn</i> 80.00	<i>X</i>
25 TO REMOVE/TRANSFER FRONT DOOR COMPONENTS.	100.00	1 JOB	<i>nn</i> 100.00	<i>X</i>
26 TO CHECK WIRING FUNCTIONS.	60.00	1 JOB	60.00	<i>2d</i>
			2,440.00	2,440.00