



SGJ4253A

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
60 Jalan Lam Huat #03 - 35/36, Singapore (737869)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : GREAT AMERICAN

Vehicle Reg. No. : SGJ4253A

OWN INSURER : AXA

Vehicle Reg. Date: 11-Jul-2006

CLAIM TYPE : TP

Make / Model : NISSAN LATIO 1.5L A

Date of Accident : 16/8/2020

Engine No. : HR15355922

Chassis No. : JN1BAAC11Z0001031

COST OF CLAIMS

Parts Cost / List Items : \$ 11,166.80

Plus/Less 30% \$ 3,350.04

Total Cost / List : \$ 7,816.76

Special Nett Items : \$ 740.00

Total Parts Amount : \$ 8,556.76

Total Labour Amount : \$ 6,800.00

Gross Total : \$ 15,356.76

GST % : 7% \$ 1,074.97

Nett Amount : \$ 16,431.73

Surveyor Name and Company :

Date of survey : _____

Part by Part / Lump Sum : _____ days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : _____

Fax No : _____

HP No : _____

This claim is handled by : PAULO

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

60 Jalan Lam Huat #03 - 35/36, Singapore (737869)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SGJ4253A**
 Vehicle Reg. Date: **11/7/2006**
 Make / Model : **NISSAN LATIO 1.5L A**
 Engine No. : **HR15355922**
 Chassis No. : **JN1BAAC11Z0001031**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	BOOTLID	/DP	\$ 787.50	/DP	
2	1	BOOTLID SPOILER	XSLC	\$ 500.20	XSLC	
3	2	BOOTLID HINGES LH/RH	/BT	\$ 130.00		
4	1	BOOTLID WEATHERSTRIP	/CRU	\$ 95.00		
5	1	BOOTLID LOCK	/Sum	\$ 120.00		
6	1	BOOTLID CHROME GARNISH	X NN	\$ 283.50		
7	1	BOOTLID EMBLEM "LATIO"	/Nec	\$ 70.00		
8	1	BOOTLID LOGO	/Nec	\$ 60.00		
9	2	NUMBER PLATE LAMP LH/RH	X NN	\$ 72.00		
10	1	BOOTLID INNER TRIM	X NN	\$ 450.00		
11	1SET	BOOTLID INNER TRIM CLIPS	X NN	\$ 20.00		
12	2	BOOTLID LAMP LH/RH	X NN	\$ 190.20		
13	1	BOOTLID STRIKER	X NN	\$ 65.00		
14	2	TAIL LAMP LH/RH	/CRU	\$ 556.00		
15	2	TAIL LAMP PANEL LH/RH	/DP	\$ 329.60		
16	2	REAR FENDER LH/RH	/CRU	\$ 2,115.20		
17	2	REAR FENDER INNER TRIM LH/RH	? *	\$ 792.00		
18	2set	REAR FENDER INNER TRIM CLIPS	? *	\$ 40.00		
19	2	REAR FENDER AIR DUCT LH/RH	? *	\$ 140.00		
20	2	REAR FENDER INNER SHIELD LH/RH	/Dep	\$ 70.00		
21	1	REAR BUMPER	/CRU	\$ 532.40		
22	1SET	REAR BUMPER CLIPS	/Nec	\$ 30.00		
23	2	REAR BUMPER RETAINER LH/RH	/BR	\$ 81.80		
24	2	IMPACT BRACKET LH/RH	/DP	\$ 110.60		
25	1	REAR BUMPER CHROME GARNISH	X NN	\$ 320.00		
26	1	REAR END PANEL OUTER	/DP	\$ 434.70		
27	1	REAR END PANEL INNER	X NN			
28	1	REAR END TOP GARNISH	/CRU	\$ 120.00		
29	1	SPARETYRE PANEL	? *	\$ 847.00		
30	1	SPARETYRE TOP BOARD	? *	\$ 477.10		
31	1	REAR BUMPER LOWER COVER	X NN	\$ 772.00		
32	1	EXHAUST PIPE	/PB	\$ 490.00		
33	2	EXHAUST RUBBER MOUNTING	X NN	\$ 65.00		
34	1SET	REVERSE SENSOR	/short		\$ 300.00	
35	1	REAR END PANEL SEALANT	/Nec	\$ 80.00		40
36	1	SPARETYRE PANEL SEALANT	nec	\$ 80.00		40
37	1	REAR FENDER SEALANT	nec	\$ 80.00		80
38	1	REAR WINDSCREEN SEALANT	/Nec	\$ 150.00		60
39	1	REAR NUMBER PLATE	/CRU	\$ 50.00		35
40	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]

2

TP without prejudice.

Date: