



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 36542

GREAT AMERICAN INSURANCE COMPANY, SINGAPORE BRANCH
3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

DATE : 14/08/2020
CLAIM NO. : 11592
POLICY NO. : MC/00805171

ATTN: GREAT AMERICAN INSURANCE COMPANY, SINGAPORE
BRANCH

FROM : HASRIANAH

VEHICLE NO. : FBC2333L
MAKE/MODEL : YAM / T135

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	Repair	1.00	\$490.00	490.00
2	AXLE WHEEL FRONT / BT	REPLACE	1.00	\$33.00	33.00
3	BALL BEARING / Im	REPLACE	1.00	\$11.00	11.00
4	BALL BEARING RETAINER / MC	REPLACE	1.00	\$19.00	19.00
5	BALL RACE 1 /	REPLACE	1.00	\$14.00	14.00
6	BALL RACE 2 /	REPLACE	1.00	\$13.00	13.00
7	BALL RACE 2 /	REPLACE	1.00	\$13.00	13.00
8	BEARING /	REPLACE	2.00	\$17.00	34.00
9	BOLT /	REPLACE	2.00	\$3.00	6.00
10	BOX BATTERY / Flat.	REPLACE	1.00	\$24.00	24.00
11	BRACKET 1 / MC	REPLACE	1.00	\$7.00	7.00
12	BRACKET HANDLE BAR / BR	REPLACE	1.00	\$40.00	40.00
13	BRACKET SIDE COVER FRONT LH / MC	REPLACE	1.00	\$6.00	6.00

*36542 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2202-1-0363
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	CABLE SPEEDOMETER <i>/ Gnt.</i> P/N: 30509	REPLACE	1.00	\$19.00	19.00
15	COOLANT (MOBIL) ANTIFREEZE <i>/ ncl.</i> P/N: 60213	REPLACE	1.00	\$20.00	20.00
16	COVER SET (SPARK135) <i>/ CRA.</i> P/N: 63892	REPLACE	1.00	\$675.00	675.00
17	FOOTREST FRONT <i>/ BT</i> P/N: 29053	REPLACE	1.00	\$49.00	49.00
18	FOOTREST REAR LH <i>/ Gnt.</i> P/N: 29052	REPLACE	1.00	\$23.00	23.00
19	FORK FRONT ASSY <i>/ BR</i> P/N: 29056	REPLACE	1.00	\$444.00	444.00
20	GEAR SPEEDOMETER <i>?</i> P/N: 32353	REPLACE	1.00	\$41.00	41.00
21	GROMMET <i>/ ncl.</i> P/N: 53717	REPLACE	2.00	\$3.00	6.00
22	GUIDE AIR LH (BLACK) <i>?</i> P/N: 31888	REPLACE	1.00	\$19.00	19.00
23	HEADLAMP ASSY <i>/ Dis.</i> P/N: 29058	REPLACE	1.00	\$83.00	83.00
24	HOLDER BRAKE HOSE <i>?</i>	REPLACE	1.00	\$7.00	7.00
25	HOLDER CABLE <i>?</i> P/N: 53699	REPLACE	1.00	\$10.00	10.00
26	HOLDER SWITCH HANDLE LH <i>?</i>	REPLACE	1.00	\$2.00	2.00
27	HORN <i>/ od.</i> P/N: 53707	REPLACE	1.00	\$14.00	14.00
28	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	16.00	\$63.00 <i>40</i>	1,008.00 <i>640</i>
29	LAMP SIGNAL FRONT LH <i>/ Dis.</i> P/N: 29059	REPLACE	1.00	\$66.00	66.00
30	LAMP SIGNAL FRONT RH <i>/ Dis.</i> P/N: 29060	REPLACE	1.00	\$66.00	66.00
31	LEVER BRAKE (NISSIN SAMURAI) <i>/ BR.</i>	REPLACE	1.00	\$96.00	96.00
32	METER (UMA RACING) ASSY <i>/ Dis.</i>	REPLACE	1.00	\$315.00	315.00
33	MIRROR BAR END (SET) <i>/ BR.</i> P/N: 61738	REPLACE	1.00	\$82.00	82.00
34	PEDAL GEAR <i>/ BT.</i> P/N: 31205	REPLACE	1.00	\$33.00	33.00
35	PIPE EXHAUST (YOSHIMURA) CARBON <i>/ BT.</i>	REPLACE	1.00	\$1,794.00	1,794.00

*36542 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
36	PLATE DISC BRAKE FRONT / BT P/N: 30423	REPLACE	1.00	\$97.00	97.00
37	RADIATOR ASSY / BT. P/N: 31895	REPLACE	1.00	\$213.00	213.00
38	RIM SPORT (RCB) SP399 SET / NIS.	REPLACE	1.00	\$208.00	208.00
39	RUBBER FOOTREST FRONT / } ant. P/N: 26942	REPLACE	1.00	\$10.00	10.00
40	RUBBER FOOTREST REAR LH / } ant. P/N: 39455	REPLACE	1.00	\$12.00	12.00
41	STAY ASSY / BT. P/N: 31898	REPLACE	1.00	\$23.00	23.00
42	STICKER NUMBER PLATE FRONT (BLACK) / BT STRAIGHT P/N: 32921	REPLACE	1.00	\$21.00	21.00
43	SWITCH SIGNAL ASSY / CRA. P/N: 34411	REPLACE	1.00	\$91.00	91.00
44	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$56.00	56.00
45	VISOR / Sch.	REPLACE	1.00	\$75.00	75.00

SUB TOTAL

\$6,388.00

GST @ 7 %

\$447.16

GRAND TOTAL (SGD)

\$6,835.16

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "No Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5 Days.
Lump sum repair.

After repair photos.

Gma Qiang - 82880282

19/8/2020.

*36542 *

bizSAFE₃