

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 24 Aug 2020

## **Preliminary Advice**

|                    |                                                                                                                   |                         |              |
|--------------------|-------------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SKL711M                                                                                                         |                         |              |
| TP Vehicle No      | : GBH1775A                                                                                                        | Accident Date           | : 18/08/2020 |
| Make               | : NISSAN NV200                                                                                                    | Assignment Date         | : 19/08/2020 |
| Date of Inspection | : 20/08/2020                                                                                                      | Est. Duration of Repair | : 6 days     |
| Inspection At      | : Woon Meng Motor Pte Ltd (Bukit Batok)<br>50 Bukit Batok Street 23,, #01-06 Midview Building<br>Singapore 659578 |                         |              |

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages at the rear portion and parts claimed are consistent to the accident.

|                             |      |        |
|-----------------------------|------|--------|
| Repairer's Estimate (Gross) | :S\$ | 285.00 |
| Revised Amount              | :S\$ | 275.00 |
| Check Items (Estimated)     | :S\$ | 0.00   |
| Total                       | :S\$ | 275.00 |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

- ( ) The vehicle is economical for repair
- ( ) The vehicle is not economical for repair
- ( ) Part-by-Part repair
- ( ) Lump Sum repair
  
- ( X ) The above survey was conducted on a 'without prejudice' basis.
  
- ( X ) Remarks : Some parts items & labour are still pending prices.