

CLAIM DETAIL : PARTS				
S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER Distorted.	1	\$ 530.50	\$ 530.50
2	FRONT BUMPER TOW COVER Behind	1	\$ 15.10	\$ 15.10
3	FRONT BUMPER REINFORCEMENT Bent	1	\$ 268.80	\$ 268.80
4	FRONT BUMPER SIDE RETAINER New	2	\$ 20.40	\$ 40.80
5	FRONT BUMPER LOWER GRILLE New	1	\$ 171.60	\$ 171.60
6	FRONT ENGINE UNDER COVER torn	2	\$ 89.60	\$ 179.20
7	HEADLAMP Cacked.	2	\$ 529.50	\$ 1,059.00
8	HEADLAMP LOWER BRACKET LH Hyd	2	\$ 46.70	\$ 93.40
9	FRONT WIPER PANEL Regis	1	\$ 497.00	\$ 497.00
10	FRONT WIPER PANEL GARNISH Lt	1	\$ 195.00	\$ 195.00
11	FRONT WIPER PANEL SIDE GARNISH New	2	\$ 44.00	\$ 88.00
12	BONNET Distorted	1	\$ 464.70	\$ 464.70
13	BONNET HINGE Bent	2	\$ 62.00	\$ 124.00
14	BONNET WEATHER STRIP Not new	2	\$ 32.00	\$ 64.00
15	BONNET AIR DUCT Not new	1	\$ 95.00	\$ 95.00
16	BONNET STOPPER New	2	\$ 15.00	\$ 30.00
17	BONNET LOCK Damaged	1	\$ 76.50	\$ 76.50
18	FRONT SUPPORT PANEL Distorted.	1	\$ 574.60	\$ 574.60
19	AIR CON CONDENSER Bent	1	\$ 796.80	\$ 796.80
20	AIR CON CONDENSER MOUNTING RUBBER New	4	\$ 15.00	\$ 60.00
21	AIR CON CONDENSER BRACEKT New	2	\$ 15.00	\$ 30.00
22	RADIATOR Cacked.	1	\$ 1,207.60	\$ 1,207.60
23	RADIATOR TOP BRACKET New	2	\$ 29.20	\$ 58.40
24	RADIATOR RUBBER MOUNTING New	4	\$ 12.00	\$ 48.00
25	RADIATOR FAN MOTOR } New	1	\$ 389.80	\$ 389.80
26	RADIATOR FAN COWLING } New	1	\$ 160.60	\$ 160.60
27	RADIATOR FAN BLADE }	1	\$ 99.70	\$ 99.70
28	FRONT TEMPERATURE SENSOR Not new	1	\$ 179.60	\$ 179.60

TO : **AIG MOTOR CLAIMS DEPTS**
 VEHICLE NO : **SJY5301Z**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 16.08.20
 TIME OF ACCIDENT : 23:4010HRS

29	ECU <i>3 new</i>	1	\$ 2,200.00	\$ 2,200.00	X
30	ECU BRACKET <i>new</i>	1	\$ 69.40	\$ 69.40	X
31	ECU COVER GARNISH <i>lt</i>	1	\$ 78.30	\$ 78.30	✓
32	HORN <i>new</i>	2	\$ 89.60	\$ 179.20	X
33	BATTERY TRAY <i>new</i>	1	\$ 78.30	\$ 78.30	X
34	AIR CLEANER BOX (COMPLETE SET) <i>crushed</i>	1	\$ 694.10	\$ 694.10	✓
35	AIR CLEANER BRACKET <i>3 new</i>	2	\$ 59.20	\$ 118.40	X
36	BATTERY BRACKET <i>new</i>	1	\$ 49.70	\$ 49.70	X
37	FRONT DASHBOARD <i>torn</i>	1	\$ 986.00	\$ 986.00	✓
38	FRONT DASHBOARD SUPPORT BEAM <i>new</i>	1	\$ 580.00	\$ 580.00	X
39	FRONT DASHBOARD GLOVE COMPARTMENT <i>new</i>	1	\$ 289.20	\$ 289.20	X
40	FRONT DASHBOARD GLOVE COMPARTMENT COVER <i>new</i>	1	\$ 174.60	\$ 174.60	X
41	FRONT SAFETY BELT	2	\$ 984.20	\$ 1,968.40	✓
42	FRONT PASSENGER AIR BAG	1	\$ 2,236.80	\$ 2,236.80	✓
43	FRONT STEERING WHEEL AIR BAG <i>Activated</i>	1	\$ 1,987.70	\$ 1,987.70	✓
44	FRONT AIR BAG SENSOR	2	\$ 189.60	\$ 379.20	✓
45	FRONT AIR BAG CONTROL UNIT	1	\$ 934.30	\$ 934.30	✓
46	AIR FRONT BAG WIRE HARNESS	1	\$ 395.00	\$ 395.00	✓
47	FRONT FENDER <i>Distorted</i>	2	\$ 396.40	\$ 792.80	✓
48	FRONT FENDER INNER SHIELD <i>LH torn</i>	2	\$ 96.40	\$ 192.80	96.40
49	FRONT FENDER QUARTER GLASS GARNISH <i>new</i>	2	\$ 27.00	\$ 54.00	X
50	FRONT FENDER QUARTER GLASS C/W MOULDING RH <i>new</i>	1	\$ 295.00	\$ 295.00	X
51	FRONT WHEEL HOUSE LH <i>Repis</i>	1	\$ 986.50	\$ 986.50	X
52	FRONT WHEEL HOUSE EXTEND PANEL LH <i>Repis</i>	1	\$ 563.40	\$ 563.40	X
53	FRONT WHEEL HOUSE EXTEND SUPPORT PANEL <i>Bent</i>	1	\$ 262.70	\$ 262.70	✓
54	FRONT WINDSCREEN GLASS <i>crushed</i>	1	\$ 1,434.80	\$ 1,434.80	✓
55	FRONT WINDSCREEN MOULDING <i>new</i>	1	\$ 194.40	\$ 194.40	✓
56	ENGINE MOUNTING (SET) <i>new</i>	1	\$ 794.70	\$ 794.70	X
57	FRONT CHASSIS MEMBER LH <i>Repis</i>	1	\$ 1,426.00	\$ 1,426.00	X
58	FRONT ABS SENSOR <i>new</i>	2	\$ 263.10	\$ 526.20	X
59	FRONT CROSS MEMBER <i>Bent</i>	1	\$ 1,497.60	\$ 1,497.60	✓
60	FRONT STEERING RACK AND PINION <i>Bent</i>	1	\$ 1,148.80	\$ 1,148.80	✓
61	FRONT DRIVESHAFT <i>3 new</i>	2	\$ 976.20	\$ 1,952.40	X
62	FRONT DRIVESHAFT OIL SEAL <i>new</i>	2	\$ 75.40	\$ 150.80	X
63	FRONT KNUCKLE ARM <i>Damaged</i>	2	\$ 790.40	\$ 1,580.80	690.
64	FRONT LOWER ARM <i>Bent</i>	2	\$ 160.40	\$ 320.80	✓
65	FRONT WHEEL HUP <i>Damaged</i>	2	\$ 138.40	\$ 276.80	✓

TO : **AIG MOTOR CLAIMS DEPTS**
 VEHICLE NO : **SJY5301Z**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 16.08.20
 TIME OF ACCIDENT : 23:4010HRS

66	FRONT WHEEL HUP BEARING <i>Nu</i>	2	\$ 116.20	\$ 232.40	✓
67	FRONT LINKAGE <i>not nu</i>	2	\$ 49.80	\$ 99.60	X
68	FRONT DOOR PILLAR (OUTER) RH <i>3 Repair</i>	1	\$ 1,033.90	\$ 1,033.90	X
69	FRONT DOOR PILLAR (INNER) RH	1	\$ 569.40	\$ 569.40	X
70	FRONT DOOR SIDE MIRROR RH <i>Not nu</i>	1	\$ 758.50	\$ 758.50	X
71	FRONT DOOR RH <i>Distorted</i>	1	\$ 1,050.20	\$ 1,050.20	✓
72	FRONT DOOR BLACK STICKER RH <i>Nu</i>	1	\$ 45.80	\$ 45.80	✓
73	FRONT DOOR STOPPER <i>Not Nu</i>	2	\$ 19.00	\$ 38.00	X
74	FRONT DOOR HINGE RH <i>Best</i>	2	\$ 49.20	\$ 98.40	✓
75	FRONT DOOR CHECKER RH <i>Not nu</i>	1	\$ 54.20	\$ 54.20	X
76	FRONT DOOR KEY LOCK <i>Not nu</i>	1	\$ 262.40	\$ 262.40	X
77	FRONT DOOR WIRE HARNESS RH <i>Not nu</i>	1	\$ 764.40	\$ 764.40	X
78	FRONT DOOR INNER LOCK RH <i>Turned</i>	1	\$ 262.40	\$ 262.40	✓
79	FRONT DOOR INNER TRIM RH <i>Del</i>	1	\$ 594.20	\$ 594.20	✓
80	FRONT DOOR LOCK CATCHER RH <i>Nu</i>	1	\$ 39.40	\$ 39.40	X
81	FRONT DOOR OUTER STRIP RH <i>cut</i>	1	\$ 189.70	\$ 189.70	✓
82	FRONT DOOR STEP INNER GARNISH RH <i>nu</i>	1	\$ 167.50	\$ 167.50	X
83	FRONT DOOR POWER WINDOW MOTOR RH <i>nu</i>	1	\$ 361.20	\$ 361.20	X
84	FRONT DOOR REGULATOR RH <i>Del</i>	1	\$ 246.70	\$ 246.70	✓
85	FRONT DOOR GLASS CHANNEL RH <i>Best</i>	1	\$ 59.20	\$ 59.20	✓
86	FRONT DOOR FRAME WEATHER STRIP RH <i>nu</i>	1	\$ 79.40	\$ 79.40	X
87	CENTER PILLAR INNER TRIM <i>Not nu</i>	2	\$ 79.20	\$ 158.40	X
88	ROCKER PANEL(OUTER) RH <i>Dented</i>	1	\$ 396.40	\$ 396.40	✓

25237.60

2019008

TOTAL PRICE \$ 43,009.30
 LESS 20% \$ 8,601.86
SUB TOTAL PRICE \$ 34,407.44

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Not nu</i>	1	\$ 80.00	\$ 80.00	X
2	FRONT BUMPER CLIP (SET) <i>nu</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT BUMPER LOWER LIP C/W DIFFUSER (SPECIAL TYPE) <i>Not nu</i>	1	\$ 1,800.00	\$ 1,800.00	X
4	FRONT GRILLE CLIP (SET) <i>Not nu</i>	1	\$ 50.00	\$ 50.00	X
5	FRONT GRILLE (SPECIAL TYPE) <i>Not nu</i>	1	\$ 1,200.00	\$ 1,200.00	X
6	FRONT SUPPORT PANEL SEALANT <i>Not nu</i>	1	\$ 120.00	\$ 120.00	X
7	DASHBOARD CLIP (SET) <i>nu</i>	1	\$ 150.00	\$ 150.00	X
8	FRONT WINDSCREEN SEALANT <i>3</i>	1	\$ 80.00	\$ 80.00	30
9	FRONT WINDSCREEN INNER SEAL <i>Not nu</i>	1	\$ 60.00	\$ 60.00	30
10	FRONT WINDSCREEN SOLAR FILM	1	\$ 550.00	\$ 550.00	200

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJY5301Z**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 16.08.20
 TIME OF ACCIDENT : 23:4010HRS

11	FRONT WINDSCREEN TOP STICKER <i>Nec</i>	1	\$ 350.00	\$ 350.00	<i>150</i>
12	FRONT ERP BRACKET <i>Nec</i>	1	\$ 40.00	\$ 40.00	<i>25</i>
13	FRONT FENDER QUARTER GLASS GARNISH CLIP RH(SET)	1	\$ 60.00	\$ 60.00	<i>x</i>
14	FRONT FENDER QUARTER GLASS SEALANT RH <i>Nec</i>	1	\$ 40.00	\$ 40.00	<i>✓</i>
15	FRONT FENDER QUARTER GLASS INNER SHIELD RH <i>Nec</i>	1	\$ 180.00	\$ 180.00	<i>x</i>
16	FRONT FENDER QUARTER GLASS SOLAR FILM RH <i>Nec</i>	1	\$ 150.00	\$ 150.00	<i>x</i>
17	FRONT WHEEL HOUSE SEALANT <i>Nec</i>	1	\$ 150.00	\$ 150.00	<i>x</i>
18	FRONT WHEEL HOUSE EXTEND PANEL SEALANT <i>Nec</i>	1	\$ 80.00	\$ 80.00	<i>x</i>
19	FRONT SHOCK ABSORBER (SET) (SPECIAL TYPE) <i>Best</i>	1	\$ 3,800.00	\$ 3,800.00	<i>1000</i>
20	FRONT WHEEL TYRE <i>Nec</i>	2	\$ 350.00	\$ 700.00	<i>x</i>
21	ROCKER PANEL(OUTER) SEALANT RH <i>Nec</i>	1	\$ 150.00	\$ 150.00	<i>x</i>
22	FRONT DOOR CARBON FIBRE STICKER (SPECIAL TYPE) <i>Nec</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
23	SIDE SKIRT (SET) (SPECIAL TYPE) <i>Distorted</i>	1	\$ 1,800.00	\$ 1,800.00	<i>600</i>
24	COOLANT <i>Nec</i>	1	\$ 120.00	\$ 120.00	<i>40</i>
25	BATTERY <i>Nec</i>	1	\$ 280.00	\$ 280.00	<i>x</i>
26	BRAKE OIL <i>Nec</i>	1	\$ 40.00	\$ 40.00	<i>30</i>
27	TRAMMISSION OIL <i>Nec</i>	1	\$ 380.00	\$ 380.00	<i>120</i>
28	ROOF LINING CLIP (SET) <i>Nec</i>	1	\$ 150.00	\$ 150.00	<i>x</i>
29	SPORT RIM (4PCS) (SET) <i>2 piece damaged</i>	1	\$ 1,200.00	\$ 1,200.00	<i>800</i>
30	DOOR VISOR (SET) <i>Nec</i>	1	\$ 350.00	\$ 350.00	<i>50</i>
			<i>3205</i> TOTAL	\$ 14,340.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,800.00	<i>1800</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,000.00	<i>1400</i>
3	TUFF COAT	\$ 250.00	<i>120</i>
4	WIRING, BULB CHECKING	\$ 180.00	<i>30</i>
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>60</i>
6	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>x</i>
7	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	<i>60</i>

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SJY5301Z
 MODEL : HONDA FIT
 DATE OF ACCIDENT : 16.08.20
 TIME OF ACCIDENT : 23:4010HRS

8	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
9	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
10	FRONT CHASSIS ALIGNMENT	\$ 250.00	X
11	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	✓
12	TO VACCUM AND CLEAN FRONT WINDSCREEN GLASS	\$ 250.00	X
13	REMOVE AND REPLACE DASHBOARD	\$ 650.00	220
14	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	500
15	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	100
16	TO PRESS FRONT WHEEL BEARING	\$ 120.00	X
17	FOUR WHEEL ALIGNMNET	\$ 120.00	80
18	TO LIFT UP AND REFIX ENGINE	\$ 650.00	X
19	REMOVE / REFIX AND REPROGRAMMING ECU	\$ 150.00	X
20	REMOVE AND REFIX FRONT PILLAR QUARTER GLASS	\$ 80.00	40
21	TRANFER FRONT DOOR MECHANISM	\$ 80.00	✓
22	RESET AUDIO SYSTEM	\$ 350.00	X
23	RESET ENGINE LIGHT	\$ 350.00	X
24	RESET ABS LIGHT	\$ 350.00	X
25	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL

\$10,620.00

4670

TO : **AIG MOTOR CLAIMS DEPTS**
VEHICLE NO : **SJY5301Z**
MODEL : **HONDA FIT**
DATE OF ACCIDENT : **16.08.20**
TIME OF ACCIDENT : **23:4010HRS**

ESTIMATE REPORT

TOTAL PARTS COST : \$ 48,747.44
TOTAL LABOUR COST : \$ 10,620.00
TOTAL REPAIR COST : \$ 59,367.44

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY
HP : 9856 4815

total 28065.08
2/s: 14K (Nett Value)
21 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: